

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 29484	Main Sti	reet: SETTLEMYER_CT	Cross	Street:	WILORA_LANDING_R	RD		Location:	NE	
ADA ID: 19EFD8EBF38	A Ramp Type: PerpDiag		Initial	Initial Pass/Fail: Fail Overall Compliance			nce: N	o Severity Score:	18.75	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
and all and a set	SETTLEMER OF	Possible Solutions:		Compliance Description Data Compliar			liance Description	Data		
		Remove & Replace Curb Ramp Wit Two New Directional Ramps or Equivalent.	With	N/A	Ramp Length (in)	97.0	Yes	Ramp Slope (%)	5.5	
				No	Ramp Width (in)	34.5	No	Ramp XSlope (%)	4.0	
-16				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
againer - 11				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
8				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
		Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
	<u>€</u>			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
				N/A	Shared Landing?	N/A				
Contraction of the second s	I COLE I FI	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
		R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Contract of the local division of the	NE STREET, SANK	,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
					X Walk 1 Direction	To W		X Walk 2 Direction	To S	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	WILORA LANDING RD	_			X Walk 1 Slope (%)	2.5		X Walk 2 Slope (%)	7.9	
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	6.5		X Walk 2 X Slope (%)	2.7	
Street 2 Name	SETTLEMYER CT			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
Stop Condition-Street 1	StopSign				Road Slope (%)	3.9	N/A	Clear Space?	N/A	
					Road X Slope (%)	8.2	N/A	Clear Space to XWalk (in)	N/A	
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
		Total Cost: \$	3200.00		Obstruction Type			Storm Grate/Utility Type		
						N/A			N/A	
							1		ļ	

es Surface Condition? (G/P)

Good

