cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



		_					
Intersection ID: 45438 Main S	Main Street: HENDERSON_VALLEY_LN		Cross Street: HENDERSON_CR			Location:	SW
ADA ID: 1B7A20113803 Ramp	DA ID: 1B7A20113803 Ramp Type: Perp		Initial Pass/Fail: Fail Overall Compliance: No			Severity Score:	35
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance					
	Possible Solutions:	Com	bliance Description	Data	Comp	liance Description	Data
A State of the second sec	Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	49.0	No	Ramp Slope (%)	20.0
1 Maria and a second		No	Ramp Width (in)	43.0	No	Ramp XSlope (%)	4.2
	3	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
HENDERSON VALUEY IN	de la constance	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	5	N/A	Shared Landing?	N/A			
	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	Not Found, R304.5.1, R304.2.2,	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	R304.5.3	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
			X Walk 1 Direction	To N		X Walk 2 Direction	N/A
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name HENDERSON VALLEY LN	_		X Walk 1 Slope (%)	4.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 None			X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	N/A
Street 2 Name N/A		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 N/A			Road Slope (%)	N/A	N/A	Clear Space?	N/A
			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 1	850.00	Obstruction Type			Storm Grate/Utility Type	
				N/A			N/A

s Surface Condition? (G/P)

Good

