

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

5.5

0.1

N/A

No

To E

N/A

2.3

1.6

N/A

N/A

N/A

N/A

N/A

Good

Main Street: PRESCOTT POND LN Intersection ID: 24081 Cross Street: SHARPTHORNE PL Location: NW ADA ID: 1CCDB00D3BB7 **Overall Compliance: No Severity Score:** Ramp Type: PerpDiag Initial Pass/Fail: Fail 8.75

Codes/Mitigation Info/Possible Solution

StopSign

StopSign

Field Measurements/Component Compliance

Yes

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Data

47.0

47.0

N/A

No

To S

N/A

5.2

3.2

N/A

1.0

3.9

N/A

N/A



SHARPTHORNE PL Street 1 Name Stop Condition-Street 2 PRESCOTT POND LN Street 2 Name Stop Condition-Street 1

Possible Solutions: Compliance Description N/A Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1

Total Cost: 3200.00

No Ramp Width (in) N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Landing Length (in) N/A Landing Width (in) N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A **Gutter Ponding?** N/A Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction N/A X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) N/A Ramp inside XWalk1? Road Slope (%) Road X Slope (%) N/A Any Obstructions? **Obstruction Type**

Ramp Length (in)



