

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Intersection ID: N/A Main Street: WINDSOR\_GATE\_LN Cross Street: W T HARRIS BV Location: NW ADA ID: 1D03DC326C40 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 13.75

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 WINDSOR GATE LN StopSign W T HARRIS BV None

**Remove & Replace Curb Ramp With** Two New Directional Ramps or Equivalent.

Possible Solutions:

Surveyor Notes: N/A PROW/ADA: Not Found, R304.2.2, R304.5.3 Total Cost: 3200.00

| Compliance Description Data Compliance Description Data |                      |                       |            |     |                             |       |
|---|----------------------|-----------------------|------------|-----|-----------------------------|-------|
| •   | N/A Ramp Length (in) |                       | 63.0       | No  | Ramp Slope (%)              | 10.8  |
|   | Yes                  | Ramp Length (in)      | 56.0       | No  | Ramp XSlope (%)             | 3.1   |
|   | N/A                  | ,                     | N/A        | N/A | ,                           | N/A   |
|   | N/A<br>N/A           | Flare Type LT         | N/A<br>N/A |     | Flare Stone BT (%)          | N/A   |
|   |                      | Flare Slope LT (%)    |            | N/A | Flare Slope RT (%)          |       |
|   | N/A                  | Flare Traversable LT? | N/A        | N/A | Flare Traversable RT?       | N/A   |
|   | N/A                  | Landing Length (in)   | N/A        | N/A | DWS Provided?               | N/A   |
|   | N/A                  | Landing Width (in)    | N/A        | N/A | DWS Contrast?               | N/A   |
|   | N/A                  | Landing Slope (%)     | N/A        | N/A | DWS Length (in)             | N/A   |
|   | N/A                  | Landing X Slope (%)   | N/A        | N/A | DWS Full Width?             | N/A   |
|   | N/A                  | Landing Curb? (Y/N)   | N/A        | N/A | DWS Offset (in)             | N/A   |
|   | N/A                  | Shared Landing?       | N/A        |     |                             |       |
|   | N/A                  | Gutter Ponding?       | N/A        | N/A | Gutter Slope (%)            | N/A   |
| ı   | N/A                  | Gutter Lip Ht (in)    | N/A        | N/A | Gutter X Slope (%)          | N/A   |
|   | N/A                  | Painted X Walk1?      | No         | N/A | Painted X Walk2?            | No    |
|   |                      | X Walk 1 Direction    | To SE      |     | X Walk 2 Direction          | To NE |
|   | N/A                  | X Walk 1 Width (in)   | N/A        | N/A | X Walk 2 Width (in)         | N/A   |
|   |                      | X Walk 1 Slope (%)    | 3.7        |     | X Walk 2 Slope (%)          | 5.0   |
|   |                      | X Walk 1 X Slope (%)  | 2.6        |     | X Walk 2 X Slope (%)        | 3.5   |
|   | N/A                  | Ramp inside XWalk1?   | N/A        | N/A | Ramp inside XWalk2?         | N/A   |
|   |                      | Road Slope (%)        | 1.6        | N/A | Clear Space?                | N/A   |
|   |                      | Road X Slope (%)      | 6.7        | N/A | Clear Space to XWalk (in)   | N/A   |
|   | N/A                  | Any Obstructions?     | N/A        | N/A | Storm Grate/Utility Hazard? | N/A   |
|   |                      | Obstruction Type      |            |     | Storm Grate/Utility Type    |       |
|   |                      |                       | N/A        |     |                             | N/A   |
|   |                      |                       |            | Yes | Surface Condition? (G/P)    | Good  |
| 2504  | 965W. 77             |                       | '          | •   | ,                           |       |





