


Intersection ID: 10026804		Main Street: FOREST_POINT_CR		Cross Street: N/A		Location:		NE			
ADA ID: 1D9AF9F0993A		Ramp Type: PerpDiag		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 46.25			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance							
<div><p>Street 1 Name FOREST POINT CR</p><p>Stop Condition-Street 2 None</p><p>Street 2 Name ENTRANCE</p><p>Stop Condition-Street 1 StopSign</p></div>				Possible Solutions:		Compliance		Description		Data	
				Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A		Ramp Length (in)		71.0	
Surveyor Notes:				N/A		No		Ramp Width (in)		38.0	
				PROW/ADA:		N/A		Flare Type LT		N/A	
Not Found, R304.5.1, R304.2.2, R304.5.3				N/A		N/A		Flare Slope LT (%)		N/A	
				N/A		N/A		Flare Slope RT (%)		N/A	
Total Cost:				\$ 3200.00		N/A		Flare Traversable LT?		N/A	
				N/A		N/A		Flare Traversable RT?		N/A	
				N/A		N/A		DWS Provided?		N/A	
				N/A		N/A		DWS Contrast?		N/A	
				N/A		N/A		DWS Length (in)		N/A	
				N/A		N/A		DWS Full Width?		N/A	
				N/A		N/A		DWS Offset (in)		N/A	
				N/A		N/A		DWS Offset (in)		N/A	
				N/A		N/A		Gutter Slope (%)		N/A	
				N/A		N/A		Gutter X Slope (%)		N/A	
				N/A		No		Painted X Walk2?		No	
				N/A		N/A		Painted X Walk2?		No	
				N/A		To NW		X Walk 2 Direction		To SW	
				N/A		N/A		X Walk 2 Width (in)		N/A	
				3.9				X Walk 2 Slope (%)		2.5	
				1.0				X Walk 2 X Slope (%)		3.7	
				N/A		N/A		Ramp inside XWalk2?		N/A	
				1.5		N/A		Clear Space?		N/A	
				3.7		N/A		Clear Space to XWalk (in)		N/A	
				N/A		N/A		Storm Grate/Utility Hazard?		N/A	
				N/A		N/A		Storm Grate/Utility Type		N/A	
				N/A		N/A		Storm Grate/Utility Type		N/A	
				N/A		Yes		Surface Condition? (G/P)		Good	
				N/A		N/A		Surface Condition? (G/P)		Good	

