## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 18033 Main Street: CHARLESTOWNE_MANOR_DRCross Street: WORCASTER_PL Location: N									
ADA ID: 1D9E9D4FDDF2 Ramp Type: Directional1				Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	8.75
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
8		Possible Solutions:		Compliance Description		Data Compliance Description		Data	
1 ALAN AND AND AND AND AND AND AND AND AND A	- //	Remove & Replace Entire Ra	amp.	N/A	Ramp Length (in)	95.0	N/A	Grade Break?	N/A
A A A A A A A A A A A A A A A A A A A	Longer 1	-	-	No	Ramp Width (in)	45.0	N/A	Grade Break Slope (%)	0.0
	· //./.			Yes	Ramp Slope (%)	2.6	N/A	Grade Break XSlope (%)	0.0
the second second	19			Yes	Ramp XSlope (%)	1.1			
A A A A A A A A A A A A A A A A A A A	8			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
102	A BERT			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0
A LAND CON		Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
5. 50°	astra L	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A
A ALLA				N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A
S 11 2 1				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A
	S ANC	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A
		R304.5.1		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A
	and the states			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A
The ten of	and the state			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A
- Maria	de la			N/A	Painted X Walk1?	No		Road Slope (%)	1.7
Street 1 Name	WORCASTER PL				X Walk 1 Direction	To SE		Road X Slope (%)	1.5
Stop Condition-Street 1	None				X Walk 1 Width (in)	N/A		Clear Space?	N/A
Street 2 Name	N/A				X Walk 1 Slope (%)	1.7	N/A	Clear Space to XWalk (in)	N/A
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	1.5	N/A	Storm Grate/Utility Hazard?	N/A
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type	
				N/A	Any Obstructions?	N/A			N/A
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good
						N/A	N/A	Curb Slope (%)	32.9

