

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

7.2

2.0

N/A

Good

Intersection ID: 9589 Main Street: FLOWERS CT Cross Street: WOODHILL MANOR CT Location: SE

Severity Score: ADA ID: 1EC8CA3F1280 Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No** 8.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Data

49.5

36.5

N/A

No

To W

N/A

2.8

0.1

N/A

N/A

N/A

N/A

N/A



WOODHILL MANOR CT Street 1 Name Stop Condition-Street 2 None N/A Street 2 Name Stop Condition-Street 1 N/A Possible Solutions: Compliance Description N/A Remove & Replace Entire Ramp. No Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1

N/A Total Cost: 1850.00

Ramp Width (in) N/A Flare Type LT N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Landing Length (in) N/A Landing Width (in) Landing Slope (%) Landing X Slope (%) Landing Curb? (Y/N) Shared Landing? **Gutter Ponding?** Gutter Lip Ht (in) Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? Road Slope (%) Road X Slope (%) Any Obstructions?

Ramp Length (in)

Obstruction Type



