cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Good

2.6

Storm Grate/Utility Type

Surface Condition? (G/P)

Curb Slope (%)

Yes

Intersection ID: 46765	Cross	Cross Street: MISSIONARY_AV				Location:	NW			
ADA ID: 1F7CE2698FAC	Ramp Type: Combination1Diag Ini				tial Pass/Fail: Fail Overall Compliance				o Severity Score:	0
Codes/Mitig	ation Info	/Possible Solution				Field Measure	ments/C	ompo	nent Compliance	
		Possible Solutions:		Compliance Description		Data Compliance Description		bliance Description	Data	
1 the submitted of		Remove & Replace Cu	urb Ramp With		N/A	Ramp Length LT (in)	58.5	N/A	Ramp Length RT (in)	51.5
March Mark		Two New Directional F				Ramp Width LT (in)	60.5	Yes	Ramp Width RT (in)	60.0
All It I want I will the		Equivalent.			No	Ramp Slope LT (%)	10.4	No	Ramp Slope RT (%)	8.6
					No	Ramp XSlope LT (%)	4.8	No	Ramp XSlope RT (%)	4.4
	、 代生 印				N/A	Ramp Length (in)	75.0	No	Ramp Slope (%)	9.3
	LE AN				No	Ramp Width (in)	37.0	No	Ramp XSlope (%)	6.9
		Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
E 23	M La Car	N/A			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
FRIENDSHIP_VILLAGE_IPL					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
A AV					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
6 6 S	All and				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	1.184 - 4	PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
States the states of	R304.5.1, R304.2.2, R304.5.3, R304.3.2			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
the of a state of the second				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
MARY STREET, MARY STREET, STRE				N/A	Shared Landing?	N/A				
Windowski wa shakara				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	None				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Stop Condition-Street 1 FRIENDSHIP VI	LLAGE PL				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
Street 2 Name	None					X Walk 1 Direction	To S		X Walk 2 Direction	To E
Stop Condition-Street 2 MISSI	ONARY AV					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
						X Walk 1 Slope (%)	4.5		X Walk 2 Slope (%)	0.5
						X Walk 1 X Slope (%)	4.2		X Walk 2 X Slope (%)	3.4
		Total Cost:	\$	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
						Road Slope (%)	6.3		Clear Space?	N/A
						Road X Slope (%)	1.0	N/A	Clear Space to XWalk (in)	N/A
			R Carl	Tastan				N/A	Any Obstruction?	N/A
	Constant of		- 8						Obstruction Type	
the second se						and the second second				N/A
								N/A	Storm Grate/Utility Hazard?	N/A





