cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

| | | - | | | | | | | |
|---|-----------------------------|--|---------|---|--|-------|-----------------------------|-----------------------------|-------|
| Intersection ID: 50707 | Main Str | Main Street: CONGREGATION_DR | | | Cross Street: BROTHERLY_LN | | | | NW |
| ADA ID: 1F85119BB300 | Ramp Ty | Ramp Type: PerpDiag | | | Initial Pass/Fail: Fail Overall Compliance: No | | | | 21.25 |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | |
| | | Possible Solutions: | | Compliance Description | | | Data Compliance Description | | Data |
| | | Remove & Replace Curb Ramp Wi Two New Directional Ramps or Equivalent. | mp With | N/A | Ramp Length (in) | 48.0 | No | Ramp Slope (%) | 11.3 |
| | | | | No | Ramp Width (in) | 47.5 | Yes | Ramp XSlope (%) | 1.9 |
| | | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| E. | | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| and the second | | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| 100 m | CAN !! | | | N/A | Shared Landing? | N/A | | | |
| | al - 1 - 6 | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| | Not Found, R304.5.1, R304.2 | 2.2 | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| 11/1 | 1 TUNE | | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| | | | | | X Walk 1 Direction | To SE | | X Walk 2 Direction | To NE |
| | | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name | BROTHERLY LN | - | | | X Walk 1 Slope (%) | 0.1 | | X Walk 2 Slope (%) | 2.4 |
| Stop Condition-Street 2 | None | | | | X Walk 1 X Slope (%) | 1.4 | | X Walk 2 X Slope (%) | 2.9 |
| Street 2 Name | CONGREGATION DR | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | StopSign | | | | Road Slope (%) | 2.0 | N/A | Clear Space? | N/A |
| | | | | | Road X Slope (%) | 0.7 | N/A | Clear Space to XWalk (in) | N/A |
| | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: \$ | 3200.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | | N/A | | | N/A |
| | | | | | | | | | |