## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



		•							
Intersection ID: 5291	Main Street: LEX_DR			eet:	MARY_ALEXANDER_	Location:	NW		
ADA ID: 220B1143B292	Ramp Type: BlendTrans2			s/Fa	il: Fail Overall C	o Severity Score:	12.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
6 1 00 and 1 1	at 11/10-3	Possible Solutions:	C					mpliance Description Data	
8	11/10	Remove & Replace Curb Ramp		/A	Ramp Length (in)	58.0	Yes	BlendTrans Slope (%)	0.9
ST ST		Two New Directional Ramps or Equivalent.		es	Ramp Width (in)	56.0	No	BlendTrans XSlope (%)	5.8
			N	/ <b>A</b>	Flare Type LT	N/A	N/A	Flare Type RT	N/A
A GE & SAME	NO 11 Paras		N	/ <b>A</b>	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N	/ <b>A</b>	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Carrow Carlo			N	/ <b>A</b>	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
Res I		Surveyor Notes:	N	/ <b>A</b>	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the second secon		N/A	N	/ <b>A</b>	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N	/ <b>A</b>	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	6. S. S.		N	/ <b>A</b>	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
8	12 × 11 - 12		N	/ <b>A</b>	Shared Landing?	N/A			
A Rahuran The		PROW/ADA:	N	/ <b>A</b>	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		Not Found, R304.5.3	Ν	/ <b>A</b>	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	1 A AL		N	/ <b>A</b>	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
				X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
	Carl Barris				X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A
Street 1 Name N	ARY ALEXANDER RD	-			X Walk 1 Slope (%)	3.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 1	None				X Walk 1 X Slope (%)	3.8		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N	/ <b>A</b>	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 2	N/A				Road Slope (%)	3.8		Clear Space?	N/A
					Road X Slope (%)	3.3	N/A	Clear Space to XWalk (in)	N/A
			N	/ <b>A</b>	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
					2.	N/A			N/A
							1		







Yes

No

Surface Condition? (G/P)

Curb Slope (%)

Good

7.7