

## **Access Compliance Report Public Rights-of-Way** (Curb Ramps)



Data

7.2

0.2

N/A

No

N/A

0.5

2.8

N/A

N/A

N/A

N/A

N/A

Good

Intersection ID: 10014519 Main Street: UNIVERSITY POINTE BV Cross Street: N/A Location: Ε

Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** ADA ID: 2433D72B3FA3 Ramp Type: PerpDiag 8.75

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

**Obstruction Type** 

Flare Traversable LT?

Flare Type LT

## **Codes/Mitigation Info/Possible Solution**

**ENTRANCE** 

**UNIVERSITY POINTE BV** 

StopSign

None

## Field Measurements/Component Compliance

Yes

Yes

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

**DWS Provided?** 

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Flare Traversable RT?

Data

99.0

44.0

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A

N/A



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1 Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

Possible Solutions:

N/A

PROW/ADA:

Not Found, R304.5.1

N/A No N/A N/A

Total Cost: 3200.00

**Gutter Ponding?** N/A N/A Gutter Slope (%) Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) Painted X Walk1? No N/A Painted X Walk2? X Walk 1 Direction To NW X Walk 2 Direction To SW N/A X Walk 2 Width (in) X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 2 Slope (%) 3.4 X Walk 1 X Slope (%) 3.5 X Walk 2 X Slope (%) Ramp inside XWalk1? N/A N/A Ramp inside XWalk2? Road Slope (%) 1.0 N/A Clear Space? N/A Road X Slope (%) 3.3 Clear Space to XWalk (in) Any Obstructions? N/A N/A N/A Storm Grate/Utility Hazard?

N/A

Yes





