

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

8.6

0.2

N/A

Good

Intersection ID: 10689 Main Street: MILTON_RD Cross Street: TIPPERARY_PL Location: E

ADA ID: 256BC60E5A7D Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

St.

MILTON RD

Signal

N/A

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

N/A

N/A

N/A

N/A

N/A

N/A

N/A

Yes

Clear Space?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Possible Solutions:	
Remove & Replace Entire Ramp.	ı
	I
	ı
Surveyor Notes:	
Surveyor Notes:	
N/A	
DDOM/ADA	
PROW/ADA:	
Not Found, R304.5.1, R304.2.2	ı
	ı
	ı

Compliance Description Data Compliance Description Ramp Length (in) No N/A 59.0 Ramp Slope (%) Yes Ramp XSlope (%) No Ramp Width (in) 45.0 N/A N/A Flare Type LT N/A Flare Type RT N/A N/A N/A Flare Slope RT (%) Flare Slope LT (%) N/A Flare Traversable LT? N/A N/A Flare Traversable RT? N/A N/A N/A **DWS Provided?** Landing Length (in) N/A Landing Width (in) N/A N/A **DWS Contrast?** N/A N/A N/A Landing Slope (%) DWS Length (in) N/A Landing X Slope (%) N/A N/A DWS Full Width? N/A Landing Curb? (Y/N) N/A N/A DWS Offset (in) N/A N/A Shared Landing? N/A Gutter Ponding? N/A N/A Gutter Slope (%) N/A Gutter Lip Ht (in) N/A N/A Gutter X Slope (%) N/A Painted X Walk1? Yes N/A Painted X Walk2? X Walk 1 Direction To SW X Walk 2 Direction N/A 111.5 X Walk 1 Width (in) X Walk 2 Width (in) X Walk 1 Slope (%) 3.8 X Walk 2 Slope (%) X Walk 1 X Slope (%) 3.4 X Walk 2 X Slope (%) N/A N/A Ramp inside XWalk2? Ramp inside XWalk1? Yes

Road Slope (%)

Road X Slope (%)

Any Obstructions?

Obstruction Type

Q			# E
A la			

Street 1 Name

Street 2 Name

Stop Condition-Street 2

Stop Condition-Street 1



Total Cost:



N/A

1850.00