


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 10020721	Main Street: BEATTIES_FORD_RD	Cross Street: BEATTIES_FORD_RD	Location: E
ADA ID: 26FB18316768	Ramp Type: Perp	Initial Pass/Fail: Pass	Overall Compliance: No
			Severity Score: 15.25

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance													
	Possible Solutions:		Compliance			Description			Data	Compliance			Description			Data
	Remove & Replace Entire Ramp.		N/A	Ramp Length (in)			106.0			Yes	Ramp Slope (%)			6.8		
	Remove & Replace Gutter.		Yes	Ramp Width (in)			48.0			No	Ramp XSlope (%)			2.1		
			N/A	Flare Type LT			Sloped			N/A	Flare Type RT			N/A		
			N/A	Flare Slope LT (%)			7.7			Yes	Flare Slope RT (%)			4.9		
			N/A	Flare Traversable LT?			Yes			N/A	Flare Traversable RT?			Yes		
			No	Landing Length (in)			N/A			Yes	DWS Provided?			Yes		
			No	Landing Width (in)			N/A			Yes	DWS Contrast?			Yes		
			No	Landing Slope (%)			N/A			Yes	DWS Length (in)			24.0		
			No	Landing X Slope (%)			N/A			Yes	DWS Full Width?			Yes		
Surveyor Notes:		N/A	N/A	Landing Curb? (Y/N)			No			Yes	DWS Offset (in)			0.0		
		N/A	N/A	Shared Landing?			No									
PROW/ADA:		Not Found, R304.5.3, R304.2.1, R304.2.2-Perp, R304.3.2-Para, R304.5.4	Yes	Gutter Ponding?			No			No	Gutter Slope (%)			7.5		
			Yes	Gutter Lip Ht (in)			0.0			Yes	Gutter X Slope (%)			1.3		
			N/A	Painted X Walk1?			No			N/A	Painted X Walk2?			N/A		
				X Walk 1 Direction			To W				X Walk 2 Direction			N/A		
			N/A	X Walk 1 Width (in)			N/A			N/A	X Walk 2 Width (in)			N/A		
				X Walk 1 Slope (%)			3.0				X Walk 2 Slope (%)			N/A		
				X Walk 1 X Slope (%)			0.9				X Walk 2 X Slope (%)			N/A		
			N/A	Ramp inside XWalk1?			N/A			N/A	Ramp inside XWalk2?			N/A		
				Road Slope (%)			N/A			N/A	Clear Space?			Yes		
				Road X Slope (%)			N/A			N/A	Clear Space to XWalk (in)			N/A		
			Yes	Any Obstructions?			No			Yes	Storm Grate/Utility Hazard?			No		
				Obstruction Type							Storm Grate/Utility Type					
										N/A				N/A		
										Yes	Surface Condition? (G/P)			Good		
Total Cost:		\$ 2600.00														

Total Cost: \$ 2600.00

