

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15725Main Street: CLANTON_RDCross Street: S_TRYON_STLocation: NWADA ID: 27E82E9E8FD5Ramp Type: PerpInitial Pass/Fail: Fail Overall Compliance: No Severity Score: 25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

Surface Condition? (G/P)

Good



Street 1 Name
StryON ST
Stop Condition-Street 2
Signal
Street 2 Name
N/A
Stop Condition-Street 1
N/A

Possible Solution		Field Measurements/Component Compliance					
Possible Solutions:	Comp	liance Description	Data	Complian	ce Description	Data	
Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	60.0	No R	tamp Slope (%)	8.8	
	Yes	Ramp Width (in)	48.0	No R	tamp XSlope (%)	6.6	
	N/A	Flare Type LT	N/A	N/A F	lare Type RT	N/A	
	N/A	Flare Slope LT (%)	N/A	N/A F	lare Slope RT (%)	N/A	
	N/A	Flare Traversable LT?	N/A	N/A F	lare Traversable RT?	N/A	
	N/A	Landing Length (in)	N/A	N/A D	WS Provided?	N/A	
Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A D	OWS Contrast?	N/A	
N/A	N/A	Landing Slope (%)	N/A	N/A D	WS Length (in)	N/A	
	N/A	Landing X Slope (%)	N/A	N/A	WS Full Width?	N/A	
	N/A	Landing Curb? (Y/N)	N/A	N/A D	OWS Offset (in)	N/A	
	N/A	Shared Landing?	N/A				
PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A G	Sutter Slope (%)	N/A	
Not Found, R304.2.2, R304.5.3	N/A	Gutter Lip Ht (in)	N/A	N/A G	Gutter X Slope (%)	N/A	
	N/A	Painted X Walk1?	Yes	N/A P	ainted X Walk2?	N/A	
		X Walk 1 Direction	To SE	×	Walk 2 Direction	N/A	
	N/A	X Walk 1 Width (in)	113.0	N/A X	(Walk 2 Width (in)	N/A	
		X Walk 1 Slope (%)	3.6	×	(Walk 2 Slope (%)	N/A	
		X Walk 1 X Slope (%)	8.9	×	(Walk 2 X Slope (%)	N/A	
	N/A	Ramp inside XWalk1?	Yes	N/A F	Ramp inside XWalk2?	N/A	
		Road Slope (%)	N/A	N/A C	Clear Space?	N/A	
		Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A	
	N/A	Any Obstructions?	N/A	N/A S	Storm Grate/Utility Hazard?	N/A	
Total Cost: \$ 1850.0	0	Obstruction Type		s	Storm Grate/Utility Type		
			N/A			N/A	





