

Access Compliance Report Public Rights-of-Way (Curb Ramps)



N/A

Curb Slope (%)

14.8

`````````````````````````````````								
Intersection ID: 17062	Main Str	eet: IDLEWILD_RD	Cross Street: MONROE_RD				Location:	SE
ADA ID: 2830BF10A4C2	Ramp Ty	ype: Para	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	12.5
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
		Possible Solutions:	Compliance Description Data			Compliance Description		Data
	and the second	Remove & Replace Entire Ramp	N/A	Ramp Length LT (in)	60.0	N/A	Ramp Length RT (in)	38.0
The second second			Yes	Ramp Width LT (in)	108.0	Yes	Ramp Width RT (in)	108.0
La No -El	1		No	Ramp Slope LT (%)	10.5	Yes	Ramp Slope RT (%)	1.5
DLEWILD_RD			Yes	Ramp XSlope LT (%)	1.3	Yes	Ramp XSlope RT (%)	1.0
El Otter	ę		N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	<u>0</u>		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	Solution and a second sec	Surveyor Notes:	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
E E		RT RP < 5%	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	Character and the second		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
Hon a			N/A	Shared Landing?	N/A		ζ,	
A CONTRACTOR			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
		PROW/ADA:	N/A	Gutter Lip Ht (in)	N/A		Gutter X Slope (%)	N/A
	101.31	R304.3.2	N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
	1111	1004.0.2		X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
aut the second second	1/1/1		N/A	X Walk 1 Width (in)	110.0	N/A	X Walk 2 Width (in)	N/A
AND TO ANY	11 11			X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	N/A
Street 1 Name	IDLEWILD RD	-		X Walk 1 X Slope (%)	4.0		X Walk 2 X Slope (%)	N/A
Stop Condition-Street 1	None		N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Street 2 Name	N/A			Road Slope (%)	N/A	N/A	Clear Space?	N/A
Stop Condition-Street 2	N/A			Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A		Storm Grate/Utility Hazard?	N/A
			170	Obstruction Type	17.5		Storm Grate/Utility Type	10/5
		Total Cost: \$ 10	600.00		N/A			N/A
		φ τ			11/2	Yes	Surface Condition? (G/P)	Good
						103		3000

