

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10560Main Street: ANDERSON_STCross Street: TAPPAN_PLLocation:SADA ID: 2897D772AD3FRamp Type: ParaInitial Pass/Fail: FailOverall Compliance: NoSeverity Score:10

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name TAPPAN PL
Stop Condition-Street 1 StopSign
Street 2 Name N/A
Stop Condition-Street 2 N/A

Possible Solutions:

Remove & Replace Entire Ramp.

N/
Ye

No

N/

Surveyor Notes:

LT RP < 5%

N/

N/

PROW/ADA:

R304.5.1, R304.5.3

Total Cost: \$ 1600.00

Compliance Description		Data	omponent Compliance Compliance Description		Data
N/A	Ramp Length LT (in)	44.0	N/A	Ramp Length RT (in)	56.0
Yes	Ramp Width LT (in)	48.5	No	Ramp Width RT (in)	45.0
Yes	Ramp Slope LT (%)	1.2	Yes	Ramp Slope RT (%)	5.8
No	Ramp XSlope LT (%)	3.7	No	Ramp XSlope RT (%)	4.7
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.3		X Walk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	0.5		X Walk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	2.7





