

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9555 Main Street: FARRIOR_DR Cross Street: VICKERY_DR Location: SW

ADA ID: 28B2811A88C3 Ramp Type: BlendTrans2 Initial Pass/Fail: Pass Overall Compliance: No Severity Score: 0

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 1
Street 2 Name
Stop Condition-Street 2

FARRIOR DR StopSign VICKERY DR None Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:
N/A

Not Found, R305.2



Total Cost:



3200.00

Compliance Description Data Compliance Description Data Ramp Length (in) Yes BlendTrans Slope (%) N/A 77.0 2.5 Yes Yes Ramp Width (in) 56.0 BlendTrans XSlope (%) 0.7 N/A N/A Flare Type LT Sloped Flare Type RT Sloped N/A Flare Slope LT (%) 2.6 N/A Flare Slope RT (%) 4.8 N/A Flare Traversable LT? Nο N/A Flare Traversable RT? No N/A Landing Length (in) N/A Yes DWS Provided? Yes N/A Landing Width (in) N/A Yes **DWS Contrast?** Yes N/A Yes N/A Landing Slope (%) DWS Length (in) 25.0 N/A Landing X Slope (%) N/A Yes DWS Full Width? Yes N/A Landing Curb? (Y/N) No No DWS Offset (in) 4.0 N/A Shared Landing? No **Gutter Ponding?** No Yes Gutter Slope (%) Yes 1.9 Yes Gutter Lip Ht (in) 0.0 Yes Gutter X Slope (%) 1.9 N/A Painted X Walk1? No N/A Painted X Walk2? No X Walk 1 Direction To SE X Walk 2 Direction To NE N/A N/A X Walk 1 Width (in) X Walk 2 Width (in) X Walk 1 Slope (%) 0.0 X Walk 2 Slope (%) 1.4 X Walk 1 X Slope (%) 1.7 X Walk 2 X Slope (%) 0.5 N/A N/A Ramp inside XWalk2? N/A N/A Ramp inside XWalk1? Road Slope (%) 4.6 Clear Space? Yes Road X Slope (%) 3.6 N/A Clear Space to XWalk (in) N/A No Yes Any Obstructions? Yes Storm Grate/Utility Hazard? No Obstruction Type Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good No Curb Slope (%) 6.9

