

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 13151Main Street:MERRIMAN_AVCross Street:SPRUCE_STLocation:SWADA ID: 296DFB01277FRamp Type:ParaDiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:12.5

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name SPRUCE ST
Stop Condition-Street 1 StopSign
Street 2 Name MERRIMAN AV
Stop Condition-Street 2 StopSign

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

RT RP < 5%

PROW/ADA:

R304.3.2

Total Cost: \$ 3200.00

Compliance Description Data		Compliance Description		Data	
N/A	Ramp Length LT (in)	62.0	N/A	Ramp Length RT (in)	54.0
Yes	Ramp Width LT (in)	59.0	Yes	Ramp Width RT (in)	60.0
No	Ramp Slope LT (%)	9.4	Yes	Ramp Slope RT (%)	1.2
Yes	Ramp XSlope LT (%)	1.8	Yes	Ramp XSlope RT (%)	1.5
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To NE		X Walk 2 Direction	To NW
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	4.9		X Walk 2 Slope (%)	2.0
	X Walk 1 X Slope (%)	0.6		X Walk 2 X Slope (%)	1.4
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	1.2	N/A	Clear Space?	N/A
	Road X Slope (%)	3.4	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good
			N/A	Curb Slope (%)	14.8





