

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 49696Main Street:THISTLE_FIELD_LNCross Street:MADISON_HILL_CTLocation:NEADA ID: 29ECA5826EBBRamp Type:PerpDiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:21.25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

THISTLE FIELD LN
StopSign
MADISON HILL CT
None

Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.2.2

Total Cost: \$ 3200.00

Field Measurements/Component Compliance						
	Compliance Description		Data	Compliance Description		Data
	N/A	Ramp Length (in)	47.0	No	Ramp Slope (%)	9.7
	No	Ramp Width (in)	46.5	Yes	Ramp XSlope (%)	1.2
	N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	N/A	Shared Landing?	N/A			
	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
		X Walk 1 Direction	To W		X Walk 2 Direction	To S
	N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
		X Walk 1 Slope (%)	0.6		X Walk 2 Slope (%)	2.1
		X Walk 1 X Slope (%)	1.0		X Walk 2 X Slope (%)	0.3
	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
		Road Slope (%)	0.1	N/A	Clear Space?	N/A
		Road X Slope (%)	1.5	N/A	Clear Space to XWalk (in)	N/A
	N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Obstruction Type			Storm Grate/Utility Type	
			N/A			N/A
				Yes	Surface Condition? (G/P)	Good
063						





