

Intersection ID: 10040944	Main Street: WALNUT_AV	Cross Street: N/A	Location:	NW
ADA ID: 2B9684CCDF8A	Ramp Type: Perp	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 13.75

Codes/Mitigation Info/Possible Solution	Field Measurements/Component Compliance
---	---



### Possible Solutions:

### Remove & Replace Entire Ramp.

Surveyor Notes:

**N/A**

PROW/ADA:

**Not Found, R304.2.2**

Possible Solutions:			Compliance	Description	Data	Compliance	Description	Data		
<b>Remove &amp; Replace Entire Ramp.</b>			N/A	Ramp Length (in)	63.0	No	Ramp Slope (%)	9.5		
			Yes	Ramp Width (in)	120.0	Yes	Ramp XSlope (%)	4.1		
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A		
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A		
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A		
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
Surveyor Notes: <b>N/A</b>			N/A	Shared Landing?	N/A					
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A		
				X Walk 1 Direction	To SE		X Walk 2 Direction	N/A		
			N/A	X Walk 1 Width (in)	118.0	N/A	X Walk 2 Width (in)	N/A		
				X Walk 1 Slope (%)	5.7		X Walk 2 Slope (%)	N/A		
				X Walk 1 X Slope (%)	5.0		X Walk 2 X Slope (%)	N/A		
			N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A		
				Road Slope (%)	N/A	N/A	Clear Space?	N/A		
PROW/ADA: <b>Not Found, R304.2.2</b>				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
				Obstruction Type			Storm Grate/Utility Type			
					N/A			N/A		
						Yes	Surface Condition? (G/P)	Good		
			Total Cost:			\$	1850.00			

Street 1 Name	WALNUT AV
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

Total Cost: \$ 1850.00

