

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Good

| Intersection ID: 31247 Ma | Main Street: HARRIS_COVE_DR | | treet: | KENNERLY_COVE_CT | Location: | NW | | | |
|---|---|------------|--|-----------------------|-----------|------|-----------------------------|------|--|
| ADA ID: 2CF58A2D5E82 Ramp Type: Perp | | Initial Pa | Initial Pass/Fail: Fail Overall Compliance: No | | | | o Severity Score: | 8.75 | |
| Codes/Mitigation Info/Possible Solution | | | Field Measurements/Component Compliance | | | | | | |
| | Possible Solutions: | | Compliance Description Data Compliance Descri | | | | liance Description | Data | |
| | Remove & Replace Entire Ram | n | N/A | Ramp Length (in) | 46.0 | Yes | Ramp Slope (%) | 5.9 | |
| | | P. | No | Ramp Width (in) | 47.5 | Yes | Ramp XSlope (%) | 0.8 | |
| | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | |
| Paris R. C. | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| | | | N/A | Flare Traversable LT? | N/A | | Flare Traversable RT? | N/A | |
| | | | N/A | Landing Length (in) | N/A | | DWS Provided? | N/A | |
| | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | |
| | N/A | | N/A | Landing Slope (%) | N/A | | DWS Length (in) | N/A | |
| CT. CT. | N/A | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | |
| AN CONTRACTOR OF CONTRACTOR | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | |
| ramau | | | N/A | Shared Landing? | N/A | IN/A | DWS Offset (III) | IN/A | |
| | | | N/A | - | | N/A | | N/A | |
| | PROW/ADA: | | | Gutter Ponding? | N/A | | Gutter Slope (%) | | |
| | R304.5.1 | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | |
| A F A A A A A A A A A A A A A A A A A A | 5. Contraction of the second se | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | N/A | |
| | | | | X Walk 1 Direction | To S | | X Walk 2 Direction | N/A | |
| | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | |
| Street 1 Name KENNERLY COV | /E CT | | | X Walk 1 Slope (%) | 0.5 | | X Walk 2 Slope (%) | N/A | |
| Stop Condition-Street 2 Stop | oSign | | | X Walk 1 X Slope (%) | 3.5 | | X Walk 2 X Slope (%) | N/A | |
| Street 2 Name | N/A | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | |
| Stop Condition-Street 1 | N/A | | | Road Slope (%) | N/A | N/A | Clear Space? | N/A | |
| | | | | Road X Slope (%) | N/A | N/A | Clear Space to XWalk (in) | N/A | |
| | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | |
| | Total Cost: \$ | 1850.00 | | Obstruction Type | | | Storm Grate/Utility Type | | |
| | | | | | N/A | | | N/A | |

Yes Surface Condition? (G/P)

