

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

9.2

2.9

N/A

No

To S N/A

4.5

1.8

N/A

N/A N/A

N/A

N/A

Good

Intersection ID: 54158 Main Street: SANDERS_FARM_LN Cross Street: SKIDMORE_LN Location: NW

ADA ID: 2E37A8530CE0 Ramp Type: PerpDiag Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 13.75

Codes/Mitigation Info/Possible Solution

SKIDMORE LN

SANDERS FARM LN

StopSign

None

Field Measurements/Component Compliance

No

No

N/A

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

Storm Grate/Utility Type

Surface Condition? (G/P)

Flare Traversable RT?

Flare Type RT

Data

95.0

59.5

N/A

1.5

No

To W



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

Possible Solutions:

N/A

PROW/ADA:

Not Found, R304.2.2, R304.5.3

<u> </u>	u
N/A	Ramp Length (in)
Yes	Ramp Width (in)
N/A	Flare Type LT
N/A	Flare Slope LT (%)
N/A	Flare Traversable LT?
N/A	Landing Length (in)
N/A	Landing Width (in)
N/A	Landing Slope (%)
N/A	Landing X Slope (%)
N/A	Landing Curb? (Y/N)
N/A	Shared Landing?
N/A	Gutter Ponding?
N/A	Gutter Lip Ht (in)
N/A	Painted X Walk1?
	X Walk 1 Direction
N/A	X Walk 1 Width (in)
	X Walk 1 Slope (%)
	X Walk 1 X Slope (%)
N/A	Ramp inside XWalk1?
	Road Slope (%)
	Road X Slope (%)

Obstruction Type

Compliance Description

Total Cost: \$ 3200.00

N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)
	X Walk 1 Slope (%)	3.0		X Walk 2 Slope (%)
	X Walk 1 X Slope (%)	2.8		X Walk 2 X Slope (%)
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?
	Road Slope (%)	2.0	N/A	Clear Space?
	Road X Slope (%)	1.6	N/A	Clear Space to XWalk (in)
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?

N/A





