

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

Intersection ID: 10275 Main Street: DIXON_ST		Cross Street: SOLOMON_ST			Location: E		
			Initial Pass/Fail: Fail Overall Compliance				25
· · · ·							25
Codes/Mitigation Info/Possible Solution		Field Measurements/Component Compliance					
PPF	Possible Solutions:	Comp	bliance Description			liance Description	Data
	Remove & Replace Entire Ramp.	N/A	Ramp Length (in)	52.0		Ramp Slope (%)	10.8
	6	Yes	Ramp Width (in)	48.0		Ramp XSlope (%)	6.8
		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
		N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
DEXON_ST	-	N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
La Carlo de Carlos de Carl	Surveyor Notes:	N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
	N/A	N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
HAR HE HAR		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		N/A	Shared Landing?	N/A			
L'AT TO FILL A TON	PROW/ADA:	N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	R304.2.2, R304.5.3	N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	·····,·····	N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
			X Walk 1 Direction	To W		X Walk 2 Direction	N/A
		N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name SOLOMON ST	-		X Walk 1 Slope (%)	1.3		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 None			X Walk 1 X Slope (%)	4.6		X Walk 2 X Slope (%)	N/A
Street 2 Name N/A		N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1 N/A			Road Slope (%)	N/A	N/A	Clear Space?	N/A
			Road X Slope (%)			Clear Space to XWalk (in)	N/A
		N/A	Any Obstructions?		N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$ 1	850.00	Obstruction Type			Storm Grate/Utility Type	
	······ • •			N/A			N/A

