## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 46324	Main Street: ARBOR_VISTA_DR			Cross Street: SENATOR_ROYALL_DR				Location:	SE
ADA ID: 303745784F80	Ramp T	Ramp Type: PerpDiag			ail: Fail Overall C	o Severity Score:	10		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
Possible Solutions:				Compliance Description Data C			Comp	Compliance Description	
STATION TO STATE	HAR.	Remove & Replace Curb Ramp V	Vith	N/A	Ramp Length (in)	49.0	Yes	Ramp Slope (%)	7.1
		Two New Directional Ramps or	••••	No	Ramp Width (in)	41.0	No	Ramp XSlope (%)	4.6
		Equivalent.		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
the second second second second				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
ARBOR	VISTA DR	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
the the	E CAR	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	ART			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
	A THE ST			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
	1 - M			N/A	Shared Landing?	N/A		()	
	15-1-5	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
	K	Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
	Not Found, K304.5.1, K304.5.5		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
Street 1 Name ARBOR VISTA DR				N/A	X Walk 1 Direction	To N		X Walk 2 Direction	To W
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
				10/4	X Walk 1 Slope (%)	8.8		X Walk 2 Slope (%)	2.1
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	3.2		X Walk 2 X Slope (%)	4.2
Street 2 Name	SENATOR ROYALL DR			N/A	Ramp inside XWalk1?	5.2 N/A	N/A	Ramp inside XWalk2?	4.2 N/A
Stop Condition-Street 1				N/A	Road Slope (%)	3.6	N/A	Clear Space?	N/A N/A
Stop Condition-Street 1	StopSign				,	3.6 7.6	N/A		N/A N/A
				<b>NI/A</b>	Road X Slope (%)			Clear Space to XWalk (in)	
		Tatal Cast		N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$ 3	200.00		Obstruction Type			Storm Grate/Utility Type	
						N/A			N/A

Yes Surface Condition? (G/P)

Good

