

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

9.7

1.8

N/A

N/A

Intersection ID: N/A Main Street: SOUTH BV **Cross Street: TIFFANI LN** Location: SE Initial Pass/Fail: Fail **Overall Compliance: No Severity Score:** 12.5 ADA ID: 307A39BC4730 Ramp Type: PerpDiag

Codes/Mitigation Info/Possible Solution

None

None

Field Measurements/Component Compliance

No

Yes

N/A

N/A

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

Data

71.5

59.0

N/A

N/A



Street 1 Name TIFFANI LN Stop Condition-Street 2 **SOUTH BV** Street 2 Name Stop Condition-Street 1

Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: R304.2.2

N/A Flare Slope LT (%) N/A Flare Traversable LT? N/A Landing Length (in) N/A Landing Width (in) N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A **Gutter Ponding?** N/A Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction N/A X Walk 1 Width (in) N/A N/A 3200.00

N/A

Yes

N/A

X Walk 1 Slope (%) X Walk 1 X Slope (%) Ramp inside XWalk1? Road Slope (%) Road X Slope (%) Any Obstructions? **Obstruction Type**

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Type LT

N/A N/A Flare Traversable RT? N/A N/A N/A **DWS Provided?** N/A N/A N/A **DWS Contrast?** N/A N/A N/A DWS Length (in) N/A N/A N/A DWS Full Width? N/A N/A N/A DWS Offset (in) N/A N/A N/A N/A Gutter Slope (%) N/A N/A N/A Gutter X Slope (%) N/A No N/A Painted X Walk2? No To N X Walk 2 Direction To W N/A X Walk 2 Width (in) N/A 0.7 X Walk 2 Slope (%) 0.4 3.0 X Walk 2 X Slope (%) 1.8 N/A N/A Ramp inside XWalk2? N/A 2.6 N/A Clear Space? N/A N/A 0.2 Clear Space to XWalk (in) N/A N/A N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A N/A Yes Surface Condition? (G/P) Good





Total Cost:

