cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| l | | | | | | | | | | |
|---|-------------------------------|--------------------------------|---------|------------------------|--|-----------------------------|--------------------|-----------------------------|------------|--|
| Intersection ID: 20503 | Main Str | Main Street: EMERALD_MEADOW_LN | | | Cross Street: MORNING_MIST_LN | | | Location: | | |
| ADA ID: 317A66F68A6D | Ramp Ty | Ramp Type: PerpDiag | | | nitial Pass/Fail: Fail Overall Compliand | | | o Severity Score: | 25 | |
| Codes/Mitigation Info/Possible Solution | | | | | Field Measurements/Component Compliance | | | | | |
| | C. MART | Possible Solutions: | | Compliance Description | | Data Compliance Description | | | Data | |
| 1 to the | | Remove & Replace Curb Ram | p With | N/A | Ramp Length (in) | 47.0 | No | Ramp Slope (%) | 9.1 | |
| | | Two New Directional Ramps of | | Yes | Ramp Width (in) | 48.0 | No | Ramp XSlope (%) | 5.9 | |
| | | Equivalent. | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | |
| | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| No. | | 4 | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| A A A A A A A A A A A A A A A A A A A | Ser. | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | |
| A Start | ALL AND | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | |
| the the | Yelly on | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | |
| SI DE | | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | |
| | | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | |
| | | | | N/A | Shared Landing? | N/A | | | | |
| | | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | |
| | Not Found, R304.2.2, R304.5.3 | 2 | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A | | |
| 131 | Not 1 Juna, 1304.2.2, 1304.3. | • | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No | | |
| Street 1 Name EMERALD MEADOW LN | | | | | X Walk 1 Direction | To SE | | X Walk 2 Direction | To NE | |
| | | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | |
| | | | | | X Walk 1 Slope (%) | 0.4 | | X Walk 2 Slope (%) | 5.1 | |
| Stop Condition-Street 2 | StopSign | | | | X Walk 1 X Slope (%) | 4.9 | | X Walk 2 X Slope (%) | 1.8 | |
| Street 2 Name | MORNING MIST LN | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | |
| Stop Condition-Street 1 | None | | | 10/4 | Road Slope (%) | 2.3 | N/A | Clear Space? | N/A | |
| | None | | | | Road X Slope (%) | 5.6 | N/A | Clear Space to XWalk (in) | N/A | |
| | | | | N/A | Any Obstructions? | 5.6 N/A | | Storm Grate/Utility Hazard? | N/A N/A | |
| | | Total Cost: \$ | 3200.00 | 11/7 | Obstruction Type | 17/4 | | Storm Grate/Utility Type | 11/5 | |
| | | 10tai 005t. 🗘 | 5200.00 | | Obstruction Type | N/A | | Giorni Grate/Otimity Type | N/A | |
| | | | | | | IN/A | | | IN/A | |

s Surface Condition? (G/P)

Good

