

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 9356 Mai	Main Street: E_36TH_ST			N_TRYON_ST	Location:	SE		
	Ramp Type: Perp		Initial Pass/Fail: Fail Overall Compliance: I			nce: No	o Severity Score:	21.25
Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
Possible Solutions:							liance Description	Data
	Remove & Replace Entire Ram	<b>D</b> .	N/A	Ramp Length (in)	59.5	Yes	Ramp Slope (%)	6.1
A the second of the			No	Ramp Width (in)	43.0	No	Ramp XSlope (%)	6.8
a / / / / /	at an		N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
E C IS			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
6 North			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
E E	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
<u>s</u>	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
	4		N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
a a			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
CARLES BALL	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
The second secon	Not Found, R304.5.1, R304.5.3		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
Etter of the second second			N/A	Painted X Walk1?	Yes	N/A	Painted X Walk2?	N/A
23 1 300 1 3				X Walk 1 Direction	To SW		X Walk 2 Direction	N/A
	- Abras		N/A	X Walk 1 Width (in)	110.0	N/A	X Walk 2 Width (in)	N/A
Street 1 Name E 36T	H ST			X Walk 1 Slope (%)	0.1		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2 Si	gnal			X Walk 1 X Slope (%)	3.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A		N/A	Ramp inside XWalk1?	Yes	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A			Road Slope (%)	N/A	N/A	Clear Space?	N/A
				Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
			N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
					N/A			N/A

Yes Surface Condition? (G/P)

Good

