cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

| Intersection ID: 24242 | Main St | Main Street: BEVERLY_CREST_BV | | | Cross Street: PRESCOTT_POND_LN | | | | Е |
|---|------------------|---|---|---|--------------------------------|----------------------|------|-----------------------------|------------|
| ADA ID: 3498AC740C81 | | Initial F | Initial Pass/Fail: Fail Overall Compliance: N | | | o Severity Score: | 37.5 | | |
| | | | Intian | | | | | | 0110 |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | |
| | | Possible Solutions: | | | liance Description | | | ance Description | Data |
| | | Remove & Replace Curb Ramp | With | N/A | Ramp Length (in) | 95.0 | | Ramp Slope (%) | 10.7 |
| | | Two New Directional Ramps or Equivalent. | | Yes | Ramp Width (in) | 48.0 | | Ramp XSlope (%) | 10.6 |
| | | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | and the second | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | | Surveyor Notes: | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | | N/A | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| TAVAR | | а 5 | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| | REAL | | | N/A | Shared Landing? | N/A | | | |
| <u>s</u> | VEV. | PROW/ADA: | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| A A A A | a the second | Not Found, R304.2.2, R304.5.3 | | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| Sec. 19 1 Martin | and the | | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| | They are the | | | | X Walk 1 Direction | To NW | | X Walk 2 Direction | To SW |
| LE LE AND | Bartel Dave & | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name | PRESCOTT POND LN | - | | | X Walk 1 Slope (%) | 0.9 | | X Walk 2 Slope (%) | 9.9 |
| Stop Condition-Street 2 | StopSign | | | | X Walk 1 X Slope (%) | 8.5 | | X Walk 2 X Slope (%) | 6.7 |
| Street 2 Name | BEVERLY CREST BV | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | None | | | 104 | Road Slope (%) | 8.2 | | Clear Space? | N/A |
| | NONE | | | | Road X Slope (%) | 5.4 | | Clear Space to XWalk (in) | N/A |
| | | | | N/A | Any Obstructions? | 5.4 N/A | | Storm Grate/Utility Hazard? | N/A N/A |
| | | Total Coat: | 2200.00 | IN/A | • | n/A | N/A | • | IN/A |
| | | Total Cost: \$ | 3200.00 | | Obstruction Type | N 1/ A | | Storm Grate/Utility Type | N//A |
| | | | | | | N/A | | | N/A |

