

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10570 Main Street: HERRIN_AV **Cross Street: HOLT_ST** Location: NE **Overall Compliance: No** ADA ID: 34A169F8B8E1 Ramp Type: BlendTrans2 Initial Pass/Fail: Fail Severity Score: 33.75

Codes/Mitigation Info/Possible Solution



HOLT ST Street 1 Name Stop Condition-Street 1 StopSign Street 2 Name N/A Stop Condition-Street 2 N/A Remove & Replace Curb Ramp With **Two New Directional Ramps or** Equivalent.

Surveyor Notes:				N/A
N/A				N/A
				N/A
				N/A
				N/A
PROW/ADA:				N/A
Not Found,	R304.5.1, R30	4.5.3	3	N/A
				N/A
				N/A
				N/A
Total Cost:		\$	3200.00	





Field Measurements/Component Compliance								
Compl	iance Description	Data	Comp	liance	Description	Data		
N/A	Ramp Length (in)	93.0	Yes	Blend	Trans Slope (%)	4.7		
No	Ramp Width (in)	46.5	No	Blend	Trans XSlope (%)	7.7		
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A		
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A		
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A		
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A		
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A		
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A		
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A		
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A		
N/A	Shared Landing?	N/A						
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A		
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A		
N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	N/A		
	X Walk 1 Direction	To SE		X Wa	lk 2 Direction	N/A		
	X Walk 1 Width (in)	N/A		X Wa	lk 2 Width (in)	N/A		
	X Walk 1 Slope (%)	2.3		X Wa	lk 2 Slope (%)	N/A		
	X Walk 1 X Slope (%)	1.4		X Wa	lk 2 X Slope (%)	N/A		
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A		
	Road Slope (%)	1.4		Clear	Space?	N/A		
	Road X Slope (%)	2.3	N/A	Clear	Space to XWalk (in)	N/A		
N/A	Any Obstructions?	N/A	N/A	Storm	Grate/Utility Hazard?	N/A		
	Obstruction Type			Storm	Grate/Utility Type			
		N/A				N/A		
			Yes	Surfa	ce Condition? (G/P)	Good		
	Links (1)		No	Curb	Slope (%)	27.9		