

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

6.8

5.5

N/A

Good

Intersection ID: N/A Main Street: VILLAGE_WALK_RD Cross Street: HOUSTON_FIELD_CT Location: NW

ADA ID: 34EB52FAACB8 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 21.25

Compliance Description

N/A

No

N/A

1850.00

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?

Flare Type LT

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

Yes

No

N/A

Yes

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Storm Grate/Utility Type

Surface Condition? (G/P)

Clear Space?

Flare Traversable RT?

Flare Type RT

Data

95.0

38.0

N/A

No

To S

N/A

1.5

5.6

N/A

N/A

N/A

N/A

N/A



Street 1 Name	HOUSTON FIELD CT
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

1 Ossible Solutions.		
Remove & Replace Entire Ramp.		
O		
Surveyor Notes:		
N/A		
PROW/ADA:		
Not Found, R304.5.1, R304.5.3		

	Landy Landy
1	

Total Cost:



