

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 28976Main Street:BANNINGTON_RDCross Street:CARMEL_COMMONS_BVLocation:SWADA ID: 35691446632FRamp Type:PerpDiagInitial Pass/Fail:FailOverall Compliance:NoSeverity Score:33.75

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



Street 1 Name
Stop Condition-Street 2
Street 2 Name
Stop Condition-Street 1

BANNINGTON RD StopSign CARMEL COMMONS BV None Possible Solutions:

Remove & Replace Curb Ramp With
Two New Directional Ramps or
Equivalent.

Surveyor Notes:
N/A

PROW/ADA:
R304.5.1, R304.5.3

Total Cost: \$ 3200.00

Comp	Compliance Description		Compliance		Description	Data
N/A	Ramp Length (in)	96.0	Yes	Ramp	Slope (%)	6.5
No	Ramp Width (in)	41.0	No	Ram	XSlope (%)	10.6
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	er Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	No
	X Walk 1 Direction	To E		X Wa	lk 2 Direction	To N
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.4		X Wa	lk 2 Slope (%)	8.5
	X Walk 1 X Slope (%)	8.6		X Wa	lk 2 X Slope (%)	4.0
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	o inside XWalk2?	N/A
	Road Slope (%)	10.1	N/A	Clear	Space?	N/A
	Road X Slope (%)	1.2	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
	Obstruction Type		l	Storn	n Grate/Utility Type	
		N/A				N/A
			Yes	Surfa	ce Condition? (G/P)	Good





