

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Cross Street: PROVIDENCE COUNTRY CLUB DR Intersection ID: 28079 Main Street: DELMAHOY DR Location: SE **Severity Score:** 12.5 **ADA ID: 3638CFF07EA2** Ramp Type: Perp Initial Pass/Fail: Fail **Overall Compliance: No**

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Landing Slope (%)

Landing X Slope (%)

Landing Curb? (Y/N)

Shared Landing?

Gutter Ponding?

Gutter Lip Ht (in)

Painted X Walk1?

X Walk 1 Direction

X Walk 1 Width (in)

X Walk 1 Slope (%)

X Walk 1 X Slope (%)

Ramp inside XWalk1?

Road Slope (%)

Road X Slope (%)

Any Obstructions?

Obstruction Type

Flare Traversable LT?

Flare Type LT

N/A

Yes

N/A

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance

No

Yes

N/A

Yes

Compliance Description

Ramp Slope (%)

Flare Type RT

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Type

Surface Condition? (G/P)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

Data

33.0

48.0

N/A

No

N/A

2.0

0.5

N/A

N/A

N/A

N/A

N/A

To SW



DELMAHOY DR Street 1 Name Stop Condition-Street 2 StopSign N/A Street 2 Name Stop Condition-Street 1 N/A Possible Solutions: Remove & Replace Entire Ramp. Surveyor Notes: N/A PROW/ADA: R304.2.2

Total Cost: 1850.00







Data

9.8

0.5

N/A

Good