cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 53635 Main St | reet: NEWBURY_GROVE_ST | Cross Str | eet. | TREMONT RIDGE C | г | | Location: | NE | |
|---|---|-------------|---|---|-----------------------------|-------|-----------------------------|-------|--|
| | | | | | | | | | |
| DA ID: 390C91578492 Ramp Type: PerpDiag | | Initial Pas | ial Pass/Fail: Fail Overall Compliance: | | | ce: N | Severity Score: | 37.5 | |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | |
| | Possible Solutions: | | Compliance Description | | Data Compliance Description | | Data | | |
| | Remove & Replace Curb Ramp W | ith N | / A | Ramp Length (in) | 96.0 | No | Ramp Slope (%) | 9.1 | |
| | Two New Directional Ramps or Equivalent. | | es | Ramp Width (in) | 48.0 | No | Ramp XSlope (%) | 9.6 | |
| | | Ν | / A | Flare Type LT | N/A | N/A | Flare Type RT | N/A | |
| | | N | / A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A | |
| | | N | / A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A | |
| | | N | / A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A | |
| | Surveyor Notes: | N | / A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A | |
| | N/A | N | / A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A | |
| | | Ν | / A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A | |
| | | Ν | / A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A | |
| | | Ν | / A | Shared Landing? | N/A | | | | |
| | PROW/ADA: | N | / A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A | |
| | Not Found, R304.2.2, R304.5.3 | Ν | / A | Gutter Lip Ht (in) | 1.5 | N/A | Gutter X Slope (%) | N/A | |
| A A A A A A A A A A A A A A A A A A A | | Ν | / A | Painted X Walk1? | No | N/A | Painted X Walk2? | No | |
| | | | | X Walk 1 Direction | To SW | | X Walk 2 Direction | To SE | |
| and the second second | | Ν | / A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A | |
| Street 1 Name NEWBURY GROVE ST | | | | X Walk 1 Slope (%) | 1.5 | | X Walk 2 Slope (%) | 7.2 | |
| Stop Condition-Street 2 StopSign | | | | X Walk 1 X Slope (%) | 5.5 | | X Walk 2 X Slope (%) | 7.5 | |
| Street 2 Name TREMONT RIDGE CT | | Ν | / A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A | |
| Stop Condition-Street 1 None | | | | Road Slope (%) | 7.3 | N/A | Clear Space? | N/A | |
| | | | | Road X Slope (%) | 2.8 | N/A | Clear Space to XWalk (in) | N/A | |
| | | Ν | I/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A | |
| | Total Cost: \$ 32 | 00.00 | | Obstruction Type | | | Storm Grate/Utility Type | | |
| | | | | | N/A | | | N/A | |

Yes Surface Condition? (G/P)

Good

