

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 15072	Main Str	eet: DILWORTH_RD_EAST	Cr	oss Street		ION AV		Location:	Е	
ADA ID: 399F4300AC7A	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Complian			nce: N	o Severity Score:	26.25	
Codes/Mitigation Info/Possible Solution					Field Measurements/Component Compliance					
		Possible Solutions:		Compliance Description		n Data	Data Compliance Description		Data	
1. 0	1 4 7	Remove & Replace Entire Ra	amp.	N/A	Ramp Length (in)	84.0	N/A	Grade Break?	N/A	
			•	Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0	
	Liels 1			No	Ramp Slope (%)	12.6	N/A	Grade Break XSlope (%)	0.0	
A CARLON AND				No	Ramp XSlope (%)	2.8				
5				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
the the the test of test o	S'HERALE			N/A	Flare Slope LT (%) N/A	N/A	Flare Slope RT (%)	0.0	
E L	SALAN S	Surveyor Notes:		N/A	Flare Traversable	LT? N/A	N/A	Flare Traversable RT?	N/A	
the second secon	A A A A	N/A		N/A	Landing Length (ir	0.0	N/A	DWS Provided?	N/A	
	Ch			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
E Contraction	Contraction of the second seco			N/A	Landing Slope (%)) 0.0	N/A	DWS Length (in)	N/A	
	AND AND			N/A	Landing X Slope (%) 0.0	N/A	DWS Full Width?	N/A	
South Lot Ca	A LON CON	PROW/ADA:		N/A	Landing Curb? (Y/	(N) N/A	N/A	DWS Offset LT (in)	N/A	
	Here .	R304.2.2, R304.5.3		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
	The Stall Stall	·		N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
	Contraction of the second			N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
	a state			N/A	Painted X Walk1?	No		Road Slope (%)	4.9	
Street 1 Name	E WORTHINGTON AV				X Walk 1 Direction	To S		Road X Slope (%)	4.0	
Stop Condition-Street 1	StopSign				X Walk 1 Width (in	n) N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%	b) 4.9	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope	(%) 4.0	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWa	lk1? N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	? N/A			N/A	
		Total Cost: \$	1600.	00	Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	8.7	

