

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Interception ID: 46295					tro of-	WESTOAK DD	Location	E		
Intersection ID: 16385	Main Street: BEAM_RD			Cross Street: WESTOAK_DR					Location:	E
ADA ID: 3AC1E1331C97	07 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	22.5	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	1 32	Possible Solutions:		Compliance Description			Data Compliance Description			Data
	The	Remove & Replac	e Entire Ramp.		N/A	Ramp Length (in)	47.0	No	Ramp Slope (%)	9.2
N. MO	A starting		•		No	Ramp Width (in)	46.0	No	Ramp XSlope (%)	3.8
	Mar.				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
	Mathin 2	4			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
Es a se a	a la				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
State	1200	N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
					N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
		8			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
The second second	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				N/A	Shared Landing?	N/A			
A Disc	The second	PROW/ADA:			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Non Non	and the second	Not Found, R304.	5.1. R304.2.2.		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
1		R304.5.3	,,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
	-					X Walk 1 Direction	To NW		X Walk 2 Direction	N/A
The second second second	-			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	BEAM RD					X Walk 1 Slope (%)	3.6		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	3.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 1	850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

Good

