

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

3.4

2.6

N/A

3.3

Good

Intersection ID: 28291 Main Street: COMMUNITY\_HOUSE\_RD Cross Street: ARDREY\_KELL\_RD Location: W

ADA ID: 3D092B308889 Ramp Type: BlendTrans1 Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 1.25

**Codes/Mitigation Info/Possible Solution** 

## Field Measurements/Component Compliance

Yes

No

N/A

Compliance Description

Flare Type RT

Flare Slope RT (%)

DWS Provided?

**DWS Contrast?** 

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Ramp inside XWalk2?

Clear Space to XWalk (in)

Storm Grate/Utility Hazard?

Clear Space?

Flare Traversable RT?

BlendTrans Slope (%)

BlendTrans XSlope (%)

Data

132.0

48.0

N/A

Yes

To SE

128.0

4.6

0.3

Yes

0.3

4.6 N/A



Street 1 Name

COMMUNITY HOUSE RD

Stop Condition-Street 1

Street 2 Name

N/A

Stop Condition-Street 2

N/A

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

Possible Solutions:

N/A

PROW/ADA:

R304.5.3

Total Cost:

N/A N/A N/A Landing Slope (%) N/A Landing X Slope (%) N/A Landing Curb? (Y/N) N/A Shared Landing? N/A **Gutter Ponding?** N/A Gutter Lip Ht (in) N/A Painted X Walk1? X Walk 1 Direction X Walk 1 Width (in) X Walk 1 Slope (%) X Walk 1 X Slope (%) N/A Ramp inside XWalk1? Road Slope (%) Road X Slope (%) N/A Any Obstructions? **Obstruction Type** 

Compliance Description

Ramp Length (in)

Ramp Width (in)

Flare Slope LT (%)

Landing Length (in)

Landing Width (in)

Flare Traversable LT?

Flare Type LT

N/A

Yes

N/A

N/A

N/A

N/A

N/A





