## cole

## **Access Compliance Report** Public Rights-of-Way (Curb Ramps)



Intersection ID: 11497	Main St	reet: MARGARET_BROWN_	ST	Cross	Street	S_IRWIN_AV			Location:	NW		
ADA ID: 3D52E91BC8F3 Ramp Type: Para			Initial	Initial Pass/Fail: Fail Overall Compliance: No				o Severity Score:	13.75			
Codes/Mitigation Info/Possible Solution						Field Measurements/Component Compliance						
		Possible Solutions:			Comp	liance Description	Description Data		Compliance Description			
		Remove & Replace Entire	e Rar	np.	N/A	Ramp Length LT (in)	32.0	N/A	Ramp Length RT (in)	44.0		
	T	•		•	Yes	Ramp Width LT (in)	48.0	Yes	Ramp Width RT (in)	48.0		
	A STATE				Yes	Ramp Slope LT (%)	0.3	No	Ramp Slope RT (%)	10.3		
	Salar and a star				Yes	Ramp XSlope LT (%)	2.0	No	Ramp XSlope RT (%)	3.3		
		Þ			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A		
OTRA IS A	Ann Park				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A		
CROP	No.	Surveyor Notes:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A		
Contraction of the second seco		NO CURB LINE			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A		
e de la companya de l					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A		
	45/152				N/A	Shared Landing?	N/A					
5	Jos A				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A		
		PROW/ADA:			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A		
	255	R304.3.2, R304.5.3			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A		
					X Walk 1 Direction	To SE		X Walk 2 Direction	N/A			
	MANY	-			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A		
					X Walk 1 Slope (%)	2.8		X Walk 2 Slope (%)	N/A			
Street 1 Name	S IRWIN AV					X Walk 1 X Slope (%)	2.7		X Walk 2 X Slope (%)	N/A		
Stop Condition-Street 1	None				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A		
Street 2 Name	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A		
Stop Condition-Street 2	N/A					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A		
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A		
						Obstruction Type			Storm Grate/Utility Type			
		Total Cost:	\$	1600.00			N/A			N/A		
								Yes	Surface Condition? (G/P)	Good		
								N/A	Curb Slope (%)	0.3		

