


Intersection ID: 10034403		Main Street: PIEDMONT_ROW_DR_SOUTH		Cross Street: N/A		Location:		NW			
ADA ID: 3DE9322FF596		Ramp Type: PerpDiag		Initial Pass/Fail: Fail		Overall Compliance: No		Severity Score: 21.25			
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance							
				Possible Solutions:		Compliance		Description		Data	
				Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.		N/A		Ramp Length (in)		50.0	
Surveyor Notes:				N/A		No		Ramp Width (in)		41.0	
						N/A		Flare Type LT		N/A	
PROW/ADA:						N/A		Flare Slope LT (%)		N/A	
						N/A		Flare Traversable LT?		N/A	
Not Found, R304.5.1, R304.2.2						N/A		Landing Length (in)		N/A	
						N/A		Landing Width (in)		N/A	
						N/A		Landing Slope (%)		N/A	
						N/A		Landing X Slope (%)		N/A	
						N/A		Landing Curb? (Y/N)		N/A	
						N/A		Shared Landing?		N/A	
						N/A		Gutter Ponding?		N/A	
						N/A		Gutter Lip Ht (in)		N/A	
						N/A		Painted X Walk1?		No	
								X Walk 1 Direction		To S	
						N/A		X Walk 1 Width (in)		N/A	
								X Walk 1 Slope (%)		4.5	
								X Walk 1 X Slope (%)		8.9	
						N/A		Ramp inside XWalk1?		N/A	
								Road Slope (%)		1.4	
								Road X Slope (%)		13.1	
						N/A		Any Obstructions?		N/A	
								Obstruction Type			
Total Cost: \$ 3200.00										N/A	
										Yes	

