

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Data

18.2

4.6

N/A

No

N/A

3.5

3.3

To NW

Cross Street: N/A Location: Intersection ID: 10038457 Main Street: SOUTHERN PINE BV

Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 26.25 ADA ID: 3E4EE840FFCC

Codes/Mitigation Info/Possible Solution

None

Field Measurements/Component Compliance

No

No

N/A

Compliance Description

Ramp Slope (%)

Ramp XSlope (%)

Flare Slope RT (%)

DWS Provided?

DWS Contrast?

DWS Length (in)

DWS Full Width?

DWS Offset (in)

Gutter Slope (%)

Gutter X Slope (%)

Painted X Walk2?

X Walk 2 Direction

X Walk 2 Width (in)

X Walk 2 Slope (%)

X Walk 2 X Slope (%)

Flare Traversable RT?

Flare Type RT

Data

48.0



ENTRANCE Street 1 Name StopSign Stop Condition-Street 2 Street 2 Name **SOUTHERN PINE BV** Stop Condition-Street 1

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.2.2, R304.5.3

Yes	Ramp Width (in)	48.0
N/A	Flare Type LT	N/A
N/A	Flare Slope LT (%)	N/A
N/A	Flare Traversable LT?	N/A
N/A	Landing Length (in)	N/A
N/A	Landing Width (in)	N/A
N/A	Landing Slope (%)	N/A
N/A	Landing X Slope (%)	N/A
N/A	Landing Curb? (Y/N)	N/A
N/A	Shared Landing?	N/A
N/A	Gutter Ponding?	N/A
N/A	Gutter Lip Ht (in)	N/A
N/A	Painted X Walk1?	No
	X Walk 1 Direction	To NE
N/A	X Walk 1 Width (in)	N/A
	X Walk 1 Slope (%)	4.3
	X Walk 1 X Slope (%)	0.1
N/A	Ramp inside XWalk1?	N/A
	Road Slope (%)	4.4
	Road X Slope (%)	4.1
N/A	Any Obstructions?	N/A
	Obstruction Type	

Compliance Description

Ramp Length (in)

N/A

Total Cost: 3200.00

	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
	Road Slope (%)	4.4	N/A	Clear Space?	N/A	
	Road X Slope (%)	4.1	N/A	Clear Space to XWalk (in)	N/A	
	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A	
	Obstruction Type			Storm Grate/Utility Type		
		N/A			N/A	
			Yes	Surface Condition? (G/P)	Good	





