cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 14014	Main St			Cross	troot				Location:	SW
	Main Street: N_SHARON_AMITY_RD			Cross Street: WILORA_LAKE_RD						
ADA ID: 3EC4705C6437	5C6437 Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				Severity Score:	21.25	
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
5-83 5A		Possible Solutions:		Compliance Description			Data	Data Compliance Description		
	ALS.	Remove & Repla	ce Entire Ramp.		N/A	Ramp Length (in)	58.0	No	Ramp Slope (%)	10.2
THE SEA					No	Ramp Width (in)	38.0	Yes	Ramp XSlope (%)	1.0
		2			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
					N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
L. S. MAKE					N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
THORA LAKE A					N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
time to the second seco		Surveyor Notes:			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
		N/A			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
and the second s		8			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
The second second					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
		5			N/A	Shared Landing?	N/A			
a formation in		PROW/ADA:			N/A	Gutter Ponding?	Yes	N/A	Gutter Slope (%)	N/A
	S. May St.	Not Found, R304	4.5.1. R304.2.2		N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
and state of the s	1 Percent		- ,		N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To E		X Walk 2 Direction	N/A	
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A	
Street 1 Name	N SHARON AMITY RD					X Walk 1 Slope (%)	3.2		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None					X Walk 1 X Slope (%)	0.1		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A				N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A					Road Slope (%)	N/A	N/A	Clear Space?	N/A
						Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
					N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost:	\$ 1	850.00		Obstruction Type			Storm Grate/Utility Type	
							N/A			N/A

Yes Surface Condition? (G/P)

Good

