cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



| Intersection ID: 11712 | Main Stre | et: ALLEN_ST | Cross | Cross Street: E_20TH_ST | | | | Location: | N |
|---|---------------------|---|-----------|---|-----------------------|-------|-------------------------------|-----------------------------|-------|
| ADA ID: 3F30245D9DCA | Ramp Type: PerpDiag | | | Initial Pass/Fail: Fail Overall Compliance: | | | nce: N | | 22.5 |
| Codes/Mitigation Info/Possible Solution | | | | Field Measurements/Component Compliance | | | | | |
| | | Possible Solutions: | | | | | a Compliance Description Data | | |
| | E. Para | Remove & Replace Curb Ramp Wi Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: Not Found, R304.5.1, R304.2.2, | mp With | N/A | Ramp Length (in) | 68.0 | No | Ramp Slope (%) | 10.2 |
| | 10 | | • | No | Ramp Width (in) | 40.0 | No | Ramp XSlope (%) | 3.1 |
| | | | | N/A | Flare Type LT | N/A | N/A | Flare Type RT | N/A |
| | | | | N/A | Flare Slope LT (%) | N/A | N/A | Flare Slope RT (%) | N/A |
| | | | | N/A | Flare Traversable LT? | N/A | N/A | Flare Traversable RT? | N/A |
| | The second | | | N/A | Landing Length (in) | N/A | N/A | DWS Provided? | N/A |
| | Atte | | | N/A | Landing Width (in) | N/A | N/A | DWS Contrast? | N/A |
| | | | | N/A | Landing Slope (%) | N/A | N/A | DWS Length (in) | N/A |
| | | | | N/A | Landing X Slope (%) | N/A | N/A | DWS Full Width? | N/A |
| | - mart | | | N/A | Landing Curb? (Y/N) | N/A | N/A | DWS Offset (in) | N/A |
| A A | | | | N/A | Shared Landing? | N/A | | | |
| | The second | | | N/A | Gutter Ponding? | N/A | N/A | Gutter Slope (%) | N/A |
| and the li | | | R304.2.2, | N/A | Gutter Lip Ht (in) | N/A | N/A | Gutter X Slope (%) | N/A |
| States In 1 1 States | | R304.5.3 | | N/A | Painted X Walk1? | No | N/A | Painted X Walk2? | No |
| | a street | | | | X Walk 1 Direction | To SW | | X Walk 2 Direction | To SE |
| | . And the second | | | N/A | X Walk 1 Width (in) | N/A | N/A | X Walk 2 Width (in) | N/A |
| Street 1 Name | E 20TH ST | | | | X Walk 1 Slope (%) | 3.2 | | X Walk 2 Slope (%) | 4.4 |
| Stop Condition-Street 2 | StopSign | | | | X Walk 1 X Slope (%) | 5.3 | | X Walk 2 X Slope (%) | 0.2 |
| Street 2 Name | ALLEN ST | | | N/A | Ramp inside XWalk1? | N/A | N/A | Ramp inside XWalk2? | N/A |
| Stop Condition-Street 1 | StopSign | | | | Road Slope (%) | 2.8 | N/A | Clear Space? | N/A |
| | | | | | Road X Slope (%) | 7.7 | N/A | Clear Space to XWalk (in) | N/A |
| | | | | N/A | Any Obstructions? | N/A | N/A | Storm Grate/Utility Hazard? | N/A |
| | | Total Cost: \$ | 3200.00 | | Obstruction Type | | | Storm Grate/Utility Type | |
| | | | | | | N/A | | | N/A |
| | | | | | | | • | | |

Yes Surface Condition? (G/P)

Good

