cole

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 27333	L Cross	Street:	BRIXHAM_HILL_AV	Location:	NW				
ADA ID: 3F88C7A5CAC5	Ramp Ty	Ramp Type: Perp			Initial Pass/Fail: Fail Overall Compliance: No				12.5
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance					
	- The state	Possible Solutions:		Compliance Description		Data Compliance Description			Data
The second		Remove & Replace Entire Ram	р.	N/A	Ramp Length (in)	96.0	No	Ramp Slope (%)	10.3
E.			•	Yes	Ramp Width (in)	57.0	Yes	Ramp XSlope (%)	0.3
6.				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
	TTTO ANY AND			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
1 H H WY	Mile 12			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
	helder and the second s	Surveyor Notes:		N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
SREAR &	and hardward	N/A		N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
A ROLL	L.			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
				N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
L.	T			N/A	Shared Landing?	N/A			
the second se	1	PROW/ADA:		N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
Not Found, R304.2.2				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	N/A
					X Walk 1 Direction	To S		X Walk 2 Direction	N/A
				N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
Street 1 Name	BRIXHAM HILL AV				X Walk 1 Slope (%)	2.0		X Walk 2 Slope (%)	N/A
Stop Condition-Street 2	None				X Walk 1 X Slope (%)	0.4		X Walk 2 X Slope (%)	N/A
Street 2 Name	N/A			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
Stop Condition-Street 1	N/A				Road Slope (%)	N/A	N/A	Clear Space?	N/A
					Road X Slope (%)	N/A	N/A	Clear Space to XWalk (in)	N/A
				N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
		Total Cost: \$	1850.00		Obstruction Type			Storm Grate/Utility Type	
					••	N/A			N/A
							Yes	Surface Condition? (G/P)	Good