

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10390	Main Street: ENDERLY_RD			Cross Street: TUCKASEEGEE_RD				Location: S		
ADA ID: 405FB04CED26	Ramp Ty	Ramp Type: Directional1			Initial Pass/Fail: Fail Overall Compliand			ice: No Severity Score: 12.5		
Codes/Mitigation Info/Possible Solution				Field Measurements/Component Compliance						
	20 734 1 1 20	Possible Solutions:		Compliance Description Data Comp				liance Description Data		
A Start Start Start		Remove & Replace Entire Ram	D.	N/A	Ramp Length (in)	42.0	N/A	Grade Break?	N/A	
	Killer Bank			Yes	Ramp Width (in)	48.0	N/A	Grade Break Slope (%)	0.0	
1. E. I.				No	Ramp Slope (%)	10.6	N/A	Grade Break XSlope (%)	0.0	
the second second	1 THE T			Yes	Ramp XSlope (%)	0.1				
TUT				N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
A CONTRACTOR				N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	0.0	
	<b>G. C.</b>	Surveyor Notes:		N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
E.	1840 ·	N/A		N/A	Landing Length (in)	0.0	N/A	DWS Provided?	N/A	
	L A			N/A	Landing Width (in)	0.0	N/A	DWS Contrast?	N/A	
Contraction of the				N/A	Landing Slope (%)	0.0	N/A	DWS Length (in)	N/A	
				N/A	Landing X Slope (%)	0.0	N/A	DWS Full Width?	N/A	
A A A A A A A A A A A A A A A A A A A	X/I and the	PROW/ADA:		N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset LT (in)	N/A	
· · · · · · · · · · · · · · · · · · ·	A	R304.2.2		N/A	Shared Landing?	N/A	N/A	DWS Offset RT (in)	N/A	
	Ca Aber			N/A	Gutter Ponding?	0.0	N/A	Gutter Slope (%)	N/A	
				N/A	Gutter Lip Ht (in)	0.0	N/A	Gutter X Slope (%)	N/A	
	N 61 1			N/A	Painted X Walk1?	No		Road Slope (%)	8.8	
Street 1 Name	TUCKASEEGEE RD				X Walk 1 Direction	To NE		Road X Slope (%)	0.4	
Stop Condition-Street 1	None				X Walk 1 Width (in)	N/A		Clear Space?	N/A	
Street 2 Name	N/A				X Walk 1 Slope (%)	8.8	N/A	Clear Space to XWalk (in)	N/A	
Stop Condition-Street 2	N/A				X Walk 1 X Slope (%)	0.4	N/A	Storm Grate/Utility Hazard?	N/A	
				N/A	Ramp inside XWalk1?	N/A		Storm Grate/Utility Type		
				N/A	Any Obstructions?	N/A			N/A	
		Total Cost: \$	1600.00		Obstruction Type		Yes	Surface Condition? (G/P)	Good	
						N/A	N/A	Curb Slope (%)	14.8	

