## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



Yes

Surface Condition? (G/P)

Good

|  |                        |                     |                 |                          | _  |                       |       |                             |                             |       |  |
|--|------------------------|---------------------|-----------------|--------------------------|--|-----------------------|-------|-----------------------------|-----------------------------|-------|--|
| Intersection ID: 16660   | Main Street: ANNLIN_AV |                     |                 | Cross Street: WEBSTER_PL |  |                       |       |                             | Location:                   | E     |  |
| ADA ID: 41FD93878659   | Ramp Type: Perp        |                     |                 | Initial P                | Initial Pass/Fail: Fail Overall Compliance: No |                       |       |                             | Severity Score:             | 58.75 |  |
| Codes/Mitigation Info/Possible Solution  |                        |                     |                 |                          | Field Measurements/Component Compliance        |                       |       |                             |                             |       |  |
|  | 24. 10                 | Possible Solutions: |                 |                          | Compliance Description                         |                       |       | Data Compliance Description |                             |       |  |
| Print  | - States               | Remove & Replac     | ce Entire Ramp  |                          | N/A  | Ramp Length (in)      | 49.0  | No                          | Ramp Slope (%)              | 12.8  |  |
| the second second second   | 14                     |                     | -               |                          | No   | Ramp Width (in)       | 47.0  | No                          | Ramp XSlope (%)             | 10.2  |  |
| He Arts  | seat with              |                     |                 |                          | N/A  | Flare Type LT         | N/A   | N/A                         | Flare Type RT               | N/A   |  |
|  | And State              |                     |                 |                          | N/A  | Flare Slope LT (%)    | N/A   | N/A                         | Flare Slope RT (%)          | N/A   |  |
|  | NA NO                  |                     |                 |                          | N/A  | Flare Traversable LT? | N/A   | N/A                         | Flare Traversable RT?       | N/A   |  |
|  | ~ 2 ~ ~                |                     |                 |                          | N/A  | Landing Length (in)   | N/A   | N/A                         | DWS Provided?               | N/A   |  |
| An An  | 1 Kan                  | Surveyor Notes:     |                 |                          | N/A  | Landing Width (in)    | N/A   | N/A                         | DWS Contrast?               | N/A   |  |
|  |                        | N/A                 |                 |                          | N/A  | Landing Slope (%)     | N/A   | N/A                         | DWS Length (in)             | N/A   |  |
|  | CP Int                 |                     |                 |                          | N/A  | Landing X Slope (%)   | N/A   | N/A                         | DWS Full Width?             | N/A   |  |
| the second secon | 1000                   |                     |                 |                          | N/A  | Landing Curb? (Y/N)   | N/A   | N/A                         | DWS Offset (in)             | N/A   |  |
| 3 ALAN   | ALT.                   |                     |                 |                          | N/A  | Shared Landing?       | N/A   |                             |                             |       |  |
|  | 1 albert               | PROW/ADA:           |                 |                          | N/A  | Gutter Ponding?       | N/A   | N/A                         | Gutter Slope (%)            | N/A   |  |
|  | C. C. C.               | Not Found, R304     | .5.1, R304.2.2, |                          | N/A  | Gutter Lip Ht (in)    | N/A   | N/A                         | Gutter X Slope (%)          | N/A   |  |
|  |                        | R304.5.3            | , ,             |                          | N/A  | Painted X Walk1?      | No    | N/A                         | Painted X Walk2?            | N/A   |  |
|  | 195 19 M               |                     |                 |                          |  | X Walk 1 Direction    | To SW |                             | X Walk 2 Direction          | N/A   |  |
| and the second s | - ATTEN                | 4                   |                 |                          | N/A  | X Walk 1 Width (in)   | N/A   | N/A                         | X Walk 2 Width (in)         | N/A   |  |
| Street 1 Name  | ANNLIN AV              |                     |                 |                          |  | X Walk 1 Slope (%)    | 7.3   |                             | X Walk 2 Slope (%)          | N/A   |  |
| Stop Condition-Street 2  | None                   |                     |                 |                          |  | X Walk 1 X Slope (%)  | 7.3   |                             | X Walk 2 X Slope (%)        | N/A   |  |
| Street 2 Name  | N/A                    |                     |                 |                          | N/A  | Ramp inside XWalk1?   | N/A   | N/A                         | Ramp inside XWalk2?         | N/A   |  |
| Stop Condition-Street 1  | N/A                    |                     |                 |                          |  | Road Slope (%)        | N/A   | N/A                         | Clear Space?                | N/A   |  |
|  |                        |                     |                 |                          |  | Road X Slope (%)      | N/A   | N/A                         | Clear Space to XWalk (in)   | N/A   |  |
|  |                        |                     |                 |                          | N/A  | Any Obstructions?     | N/A   | N/A                         | Storm Grate/Utility Hazard? | N/A   |  |
|  |                        | Total Cost:         | \$              | 1850.00                  |  | Obstruction Type      |       |                             | Storm Grate/Utility Type    |       |  |
|  |                        |                     |                 |                          |  |                       | N/A   |                             |                             | N/A   |  |

