## cole

## Access Compliance Report Public Rights-of-Way (Curb Ramps)



			1 -		/						
Intersection ID: 4305	4 Main Str	eet: CRISPIN_AV	et: CRISPIN_AV		Cross Street: JOHN_CROSLAND_JR_DR				Location:		
ADA ID: 42651BC63C	ype: Combination1Diag		Initial	Initial Pass/Fail: Fail Overall Complian				ice: No Severity Score:			
	Codes/Mitigation Info	Possible Solution			Field Measurements/Cor				omponent Compliance		
		Possible Solutions:			Compliance Description		Data Compliance Description		Data		
		Remove & Replace	Curb Ram	p With	N/A	Ramp Length LT (in)	47.0	N/A	Ramp Length RT (in)	49.0	
		Two New Direction			Yes	Ramp Width LT (in)	60.0	Yes	Ramp Width RT (in)	59.0	
	G	Equivalent.	-		Yes	Ramp Slope LT (%)	5.9	Yes	Ramp Slope RT (%)	4.0	
	Tion				Yes	Ramp XSlope LT (%)	1.3	Yes	Ramp XSlope RT (%)	1.7	
h.	NSON_BV				N/A	Ramp Length (in)	59.0	Yes	Ramp Slope (%)	8.1	
	- X:-				No	Ramp Width (in)	41.0	No	Ramp XSlope (%)	3.9	
manufacture and a second	1 - Day	Surveyor Notes:			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A	
	C. C	RT RP < 5%, DAMGAED DWS			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A	
	1				N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A	
9	r				N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A	
	1 6				N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A	
		PROW/ADA:			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A	
	1 - G	Not Found, R304.5.1, R304.5.3			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A	
					N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A	
					N/A	Shared Landing?	N/A				
	00				N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A	
Street 1 Name	None				N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A	
Stop Condition-Street 1	WILKINSON BV				N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No	
Street 2 Name	StopSign					X Walk 1 Direction	To N		X Walk 2 Direction	To W	
Stop Condition-Street 2	JOHN CROSLAND JR DR					X Walk 1 Width (in)	N/A		X Walk 2 Width (in)	N/A	
						X Walk 1 Slope (%)	6.0		X Walk 2 Slope (%)	1.3	
						X Walk 1 X Slope (%)	1.3		X Walk 2 X Slope (%)	5.7	
		Total Cost:	\$	3200.00	N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A	
						Road Slope (%)	4.8		Clear Space?	N/A	
						Road X Slope (%)	3.9	N/A	Clear Space to XWalk (in)	N/A	
			A		~			N/A	Any Obstruction?	N/A	
	· · · ·		-1-						Obstruction Type		
		Contraction of the second		A NEW						N/A	
					-			N/A	Storm Grate/Utility Hazard?	N/A	

N/A Storm Grate/Utility Hazard? N/A Storm Grate/Utility Type N/A Yes Surface Condition? (G/P) Good Curb Slope (%) 7.8





