


Access Compliance Report

Public Rights-of-Way

(Curb Ramps)

Intersection ID: 8652	Main Street: ERIE_ST	Cross Street: HATERAS_AV	Location: SE
ADA ID: 4284B950FF6A	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No
			Severity Score: 13.75

Codes/Mitigation Info/Possible Solution			Field Measurements/Component Compliance					
<div></div> <div>Street 1 NameHATERAS AV</div> <div>Stop Condition-Street 2None</div> <div>Street 2 NameERIE ST</div> <div>Stop Condition-Street 1StopSign</div> <div>Possible Solutions: Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.</div> <div>Surveyor Notes: N/A</div> <div>PROW/ADA: Not Found, R304.2.2, R304.5.3</div> <div>Total Cost:\$3200.00</div>			Compliance	Description	Data	Compliance	Description	Data
			N/A	Ramp Length (in)	42.0	No	Ramp Slope (%)	9.6
			Yes	Ramp Width (in)	48.0	No	Ramp XSlope (%)	2.9
			N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
			N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
			N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
			N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
			N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
			N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
			N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
			N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
			N/A	Shared Landing?	N/A			
			N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
			N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
			N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
				X Walk 1 Direction	To N		X Walk 2 Direction	To W
			N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
				X Walk 1 Slope (%)	6.2		X Walk 2 Slope (%)	5.9
				X Walk 1 X Slope (%)	4.6		X Walk 2 X Slope (%)	7.6
			N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	0.4	N/A	Clear Space?	N/A			
	Road X Slope (%)	9.9	N/A	Clear Space to XWalk (in)	N/A			
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A			
	Obstruction Type			Storm Grate/Utility Type				
			N/A		N/A			
			Yes	Surface Condition? (G/P)	Good			

Total Cost: \$ 3200.00

