

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: N/A Main Street: TRYON ST **Cross Street: CRESCENT SPRINGS DR** Location: SE ADA ID: 43615DB99657 Ramp Type: PerpDiag Initial Pass/Fail: Fail **Overall Compliance: No** Severity Score: 13.75

Codes/Mitigation Info/Possible Solution



Street 1 Name Stop Condition-Street 2 Street 2 Name Stop Condition-Street 1

S TRYON ST None **CRESCENT SPRINGS DR** StopSign Possible Solutions: **Remove & Replace Curb Ramp With** Two New Directional Ramps or Equivalent. Surveyor Notes: N/A PROW/ADA: R304.2.2, R304.5.3

Total Cost: 3200.00

_	Field Measuren					
	liance Description	Data	Compliance		•	Data
N/A	Ramp Length (in)	53.0	No	Ram	Slope (%)	10.4
Yes	Ramp Width (in)	48.0	No	Ram	XSlope (%)	3.8
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	er X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Paint	ed X Walk2?	No
	X Walk 1 Direction	To N		X Wa	lk 2 Direction	To SW
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	1.7		X Wa	lk 2 Slope (%)	3.3
	X Walk 1 X Slope (%)	2.6		X Wa	lk 2 X Slope (%)	2.2
N/A	Ramp inside XWalk1?	N/A	N/A	Ram	inside XWalk2?	N/A
	Road Slope (%)	0.7	N/A	Clear	Space?	N/A
	Road X Slope (%)	5.1	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storn	n Grate/Utility Hazard?	N/A
	Obstruction Type			Storn	n Grate/Utility Type	
		N/A				N/A
			Yes	Surfa	ce Condition? (G/P)	Good
		•	•		, ,	





