

Access Compliance Report Public Rights-of-Way (Curb Ramps)



Intersection ID: 10021255 Main Street: BISHOP_MADISON_LN Cross Street: N/A Location: S

ADA ID: 44028618C6B9 Ramp Type: Perp Initial Pass/Fail: Fail Overall Compliance: No Severity Score: 25

Codes/Mitigation Info/Possible Solution

Field Measurements/Component Compliance



A PERSON NAMED AND POST OF THE PARTY OF THE	The second secon
Street 1 Name	BISHOP MADISON LN
Stop Condition-Street 2	None
Street 2 Name	N/A
Stop Condition-Street 1	N/A

i ossible solution						
Possible Solutions:						
Remove & Replace Entire Ramp.						
Surveyor Notes:						
N/A						
N/A						
PROW/ADA:						
Not Found, R304.2.2, R304.5.3						

LN		
one		
N/A		
N/A		
	Total Cost:	

Comp	liance Description	Data	Comp	liance	Description	Data
N/A	Ramp Length (in)	67.0	No	Ramp	Slope (%)	9.1
Yes	Ramp Width (in)	48.0	No	Ramp	XSlope (%)	6.3
N/A	Flare Type LT	N/A	N/A	Flare	Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare	Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare	Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS	Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS	Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS	Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS	Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS	Offset (in)	N/A
N/A	Shared Landing?	N/A				
N/A	Gutter Ponding?	N/A	N/A	Gutte	r Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutte	r X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painte	ed X Walk2?	N/A
	X Walk 1 Direction	To N		X Wa	lk 2 Direction	N/A
N/A	X Walk 1 Width (in)	N/A	N/A	X Wa	lk 2 Width (in)	N/A
	X Walk 1 Slope (%)	2.6		X Wa	lk 2 Slope (%)	N/A
	X Walk 1 X Slope (%)	4.9		X Wa	lk 2 X Slope (%)	N/A
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp	inside XWalk2?	N/A
	Road Slope (%)	N/A	N/A	Clear	Space?	N/A
	Road X Slope (%)	N/A	N/A	Clear	Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm	n Grate/Utility Hazard?	N/A
	Obstruction Type		l	Storm	n Grate/Utility Type	
		N/A				N/A
			Yes	Surfa	ce Condition? (G/P)	Good







1850.00