

# Access Compliance Report

## Public Rights-of-Way

### (Curb Ramps)

|                        |                              |                               |                        |
|------------------------|------------------------------|-------------------------------|------------------------|
| Intersection ID: 22786 | Main Street: INDIAN_HILLS_LN | Cross Street: PECAN_MEADOW_CT | Location: W            |
| ADA ID: 452E2F92966D   | Ramp Type: Directional1      | Initial Pass/Fail: Fail       | Overall Compliance: No |
|                        |                              |                               | Severity Score: 21.25  |

| Codes/Mitigation Info/Possible Solution                                          |                                          |  | Field Measurements/Component Compliance |                          |              |  |
|----------------------------------------------------------------------------------|------------------------------------------|--|-----------------------------------------|--------------------------|--------------|--|
|  | Possible Solutions:                      |  | <b>Compliance</b>                       | <b>Description</b>       | <b>Data</b>  |  |
|                                                                                  | <b>Remove &amp; Replace Entire Ramp.</b> |  | <b>N/A</b>                              | Ramp Length (in)         | <b>48.0</b>  |  |
|                                                                                  |                                          |  | <b>No</b>                               | Ramp Width (in)          | <b>39.0</b>  |  |
|                                                                                  |                                          |  | <b>No</b>                               | Ramp Slope (%)           | <b>8.4</b>   |  |
|                                                                                  |                                          |  | <b>Yes</b>                              | Ramp XSlope (%)          | <b>1.3</b>   |  |
|                                                                                  |                                          |  | <b>N/A</b>                              | Flare Type LT            | <b>N/A</b>   |  |
|                                                                                  |                                          |  | <b>N/A</b>                              | Flare Slope LT (%)       | <b>N/A</b>   |  |
|                                                                                  |                                          |  | <b>N/A</b>                              | Flare Traversable LT?    | <b>N/A</b>   |  |
|                                                                                  |                                          |  | <b>N/A</b>                              | Landing Length (in)      | <b>0.0</b>   |  |
|                                                                                  |                                          |  | <b>N/A</b>                              | Landing Width (in)       | <b>0.0</b>   |  |
|                                                                                  |                                          |  | <b>N/A</b>                              | Landing Slope (%)        | <b>0.0</b>   |  |
|                                                                                  |                                          |  | <b>N/A</b>                              | Landing X Slope (%)      | <b>0.0</b>   |  |
|                                                                                  |                                          |  | <b>N/A</b>                              | Landing Curb? (Y/N)      | <b>N/A</b>   |  |
|                                                                                  |                                          |  | <b>N/A</b>                              | Shared Landing?          | <b>N/A</b>   |  |
|                                                                                  |                                          |  | <b>N/A</b>                              | Gutter Ponding?          | <b>0.0</b>   |  |
|                                                                                  |                                          |  | <b>N/A</b>                              | Gutter Lip Ht (in)       | <b>0.0</b>   |  |
|                                                                                  |                                          |  | <b>N/A</b>                              | Painted X Walk1?         | <b>No</b>    |  |
|                                                                                  |                                          |  |                                         | X Walk 1 Direction       | <b>To SE</b> |  |
|                                                                                  |                                          |  |                                         | X Walk 1 Width (in)      | <b>N/A</b>   |  |
|                                                                                  |                                          |  |                                         | X Walk 1 Slope (%)       | <b>0.2</b>   |  |
|                                                                                  |                                          |  |                                         | X Walk 1 X Slope (%)     | <b>2.0</b>   |  |
| <p>Surveyor Notes:</p> <p><b>N/A</b></p>                                         |                                          |  | <b>N/A</b>                              | Ramp inside XWalk1?      | <b>N/A</b>   |  |
|                                                                                  |                                          |  | <b>N/A</b>                              | Any Obstructions?        | <b>N/A</b>   |  |
| <p>PROW/ADA:</p> <p><b>R304.5.1, R304.2.2</b></p>                                |                                          |  |                                         | Obstruction Type         |              |  |
|                                                                                  |                                          |  | <b>Yes</b>                              | Surface Condition? (G/P) | <b>Good</b>  |  |
|                                                                                  |                                          |  | <b>N/A</b>                              | Curb Slope (%)           | <b>12.8</b>  |  |

|                         |                 |
|-------------------------|-----------------|
| Street 1 Name           | PECAN MEADOW CT |
| Stop Condition-Street 1 | StopSign        |
| Street 2 Name           | N/A             |
| Stop Condition-Street 2 | N/A             |

Total Cost: \$ 1600.00

