

Intersection ID: N/A	Main Street: PILCHER_DR	Cross Street: VILLAGE_POND_DR	Location:	NE
ADA ID: 455BFD8EA45C	Ramp Type: PerpDiag	Initial Pass/Fail: Fail	Overall Compliance: No	Severity Score: 10

Codes/Mitigation Info/Possible Solution	Field Measurements/Component Compliance
<p>1. Code 100: No visible signs of mold or moisture.</p> <p>2. Code 101: Minor moisture detected, no mold.</p> <p>3. Code 102: Moderate moisture detected, no mold.</p> <p>4. Code 103: Significant moisture detected, no mold.</p> <p>5. Code 104: Severe moisture detected, no mold.</p> <p>6. Code 105: No moisture detected, mold present.</p> <p>7. Code 106: Minor moisture detected, mold present.</p> <p>8. Code 107: Moderate moisture detected, mold present.</p> <p>9. Code 108: Significant moisture detected, mold present.</p> <p>10. Code 109: Severe moisture detected, mold present.</p>	<p>1. Field Measurements: Moisture readings, mold test results.</p> <p>2. Component Compliance: Check for proper installation, material quality.</p>



Possible Solutions:

Remove & Replace Curb Ramp With Two New Directional Ramps or Equivalent.

Surveyor Notes:

N/A

PROW/ADA:

Not Found, R304.5.1, R304.5.3

Compliance	Description	Data	Compliance	Description	Data
N/A	Ramp Length (in)	48.0	Yes	Ramp Slope (%)	7.8
No	Ramp Width (in)	47.0	No	Ramp XSlope (%)	2.5
N/A	Flare Type LT	N/A	N/A	Flare Type RT	N/A
N/A	Flare Slope LT (%)	N/A	N/A	Flare Slope RT (%)	N/A
N/A	Flare Traversable LT?	N/A	N/A	Flare Traversable RT?	N/A
N/A	Landing Length (in)	N/A	N/A	DWS Provided?	N/A
N/A	Landing Width (in)	N/A	N/A	DWS Contrast?	N/A
N/A	Landing Slope (%)	N/A	N/A	DWS Length (in)	N/A
N/A	Landing X Slope (%)	N/A	N/A	DWS Full Width?	N/A
N/A	Landing Curb? (Y/N)	N/A	N/A	DWS Offset (in)	N/A
N/A	Shared Landing?	N/A			
N/A	Gutter Ponding?	N/A	N/A	Gutter Slope (%)	N/A
N/A	Gutter Lip Ht (in)	N/A	N/A	Gutter X Slope (%)	N/A
N/A	Painted X Walk1?	No	N/A	Painted X Walk2?	No
	X Walk 1 Direction	To NW		X Walk 2 Direction	To S
N/A	X Walk 1 Width (in)	N/A	N/A	X Walk 2 Width (in)	N/A
	X Walk 1 Slope (%)	3.6		X Walk 2 Slope (%)	4.0
	X Walk 1 X Slope (%)	3.2		X Walk 2 X Slope (%)	1.4
N/A	Ramp inside XWalk1?	N/A	N/A	Ramp inside XWalk2?	N/A
	Road Slope (%)	1.2	N/A	Clear Space?	N/A
	Road X Slope (%)	6.5	N/A	Clear Space to XWalk (in)	N/A
N/A	Any Obstructions?	N/A	N/A	Storm Grate/Utility Hazard?	N/A
	Obstruction Type			Storm Grate/Utility Type	
		N/A			N/A
			Yes	Surface Condition? (G/P)	Good

Total Cost: \$ 3200.00

Street 1 Name	VILLAGE POND DR
Stop Condition-Street 2	StopSign
Street 2 Name	PILCHER DR
Stop Condition-Street 1	None

